


X Radiation between surfaces

Assumptions

1. There is a non-participating medium between surfaces, e.g. vacuum or most of gases
2. The surfaces are opaque and diffuse



Chapter 10

By E. Amani

X.1 The view factor


• Definitions

- The fraction of the radiation leaving surface i that is intercepted by surface j

$$F_{ij} = \frac{q_{i \rightarrow j}}{q_i} = \frac{q_{i \rightarrow j}}{\int A_i dA_i} \quad (1.10)$$

- If the radiosity is uniform on surface i :

$$F_{ij} = \frac{q_{i \rightarrow j}}{J_i A_i} \quad (2.10)$$



Chapter 10


By E. Amani

X.1 The view factor

• **Formulation Diffuse:** $I_{\lambda,e+r,i} = \frac{J_{\lambda,i}}{\pi}$
 $\xrightarrow{(10.9)} dq_{\lambda,i \rightarrow j} = I_{\lambda,\theta,e+r,i} d\lambda \cos \theta_i dA_i d\omega_{j-i}$ →
 or $\xrightarrow{(22.9)} dq_{i \rightarrow j} = \frac{1}{\pi} \left(\int_0^{\infty} J_{\lambda,i} d\lambda \right) \cos \theta_i dA_i d\omega_{j-i} = \frac{J_i}{\pi} \cos \theta_i dA_i d\omega_{j-i}$ →

Uniform J_i $\xrightarrow{J_i}$ $q_{i \rightarrow j} = \int dq_{i \rightarrow j} = \int \int J_i \frac{\cos \theta_i \cos \theta_j}{\pi R^2} dA_i dA_j \xrightarrow{(8.9)} \frac{dA_j \cos \theta_j}{R^2}$

$$F_{ij} = \frac{q_{i \rightarrow j}}{J_i A_i}$$



Chapter 10

By E. Amani

X.1 The view factor

A pure geometrical parameter

- Calculation**

$$F_{ij} = \frac{1}{A_i} \int_{A_i} \int_{A_j} \frac{\cos \theta_i \cos \theta_j}{\pi R^2} dA_j dA_i \quad (3.10)$$

For some surface configurations, the analytical integration of Eq. (3.10) has been reported:

Geometry	Relation
Parallel Plates with Midlines Connected by Perpendicular	$F_{ij} = \frac{[(W_i + W_j)^2 + 4]^{1/2} - [(W_j - W_i)^2 + 4]^{1/2}}{2W_i}$ $W_i = w_i/L, W_j = w_j/L$
Inclined Parallel Plates of Equal Width and a Common Edge	$F_{ij} = 1 - \sin(\alpha)$

Chapter 10 **By E. Amani**

X.1 The view factor

- Calculation**

Geometry	Relation
Parallel Cylinders of Different Radii	$F_{ij} = \frac{1}{2\pi} \left\{ \pi + [C^2 - (R+1)^2]^{1/2} - [C^2 - (R-1)^2]^{1/2} + (R-1) \cos^{-1} \left[\left(\frac{R}{C} \right) - \left(\frac{1}{C} \right) \right] - (R+1) \cos^{-1} \left[\left(\frac{R}{C} \right) + \left(\frac{1}{C} \right) \right] \right\}$ $R = r_j/r_i, S = s/r_i$ $C = 1 + R + S$
Cylinder and Parallel Rectangle	$F_{ij} = \frac{r}{s_1 - s_2} \left[\tan^{-1} \frac{s_1}{L} - \tan^{-1} \frac{s_2}{L} \right]$

Chapter 10 **By E. Amani**

X.1 The view factor

• Calculation

TABLE 13.2 View Factors for Three-Dimensional Geometries [4]

Geometry	Relation
Aligned Parallel Rectangles (Figure 13.4)	$\bar{X} = X/L, \bar{Y} = Y/L$ $F_{ij} = \frac{2}{\pi \bar{X} \bar{Y}} \left\{ \ln \left[\frac{(1 + \bar{X}^2)(1 + \bar{Y}^2)}{1 + \bar{X}^2 + \bar{Y}^2} \right]^{1/2} + \bar{X}(1 + \bar{Y}^2)^{1/2} \tan^{-1} \frac{\bar{X}}{(1 + \bar{Y}^2)^{1/2}} + \bar{Y}(1 + \bar{X}^2)^{1/2} \tan^{-1} \frac{\bar{Y}}{(1 + \bar{X}^2)^{1/2}} - \bar{X} \tan^{-1} \bar{X} - \bar{Y} \tan^{-1} \bar{Y} \right\}$
Coaxial Parallel Disks (Figure 13.5)	$R_i = r_i/L, R_j = r_j/L$ $S = 1 + \frac{1 + R_j^2}{R_i^2}$ $F_{ij} = \frac{1}{2} \{ S - [S^2 - 4(r_j/r_i)^2]^{1/2} \}$
Perpendicular Rectangles with a Common Edge (Figure 13.6)	$H = Z/X, W = Y/X$ $F_{ij} = \frac{1}{\pi W} \left(W \tan^{-1} \frac{1}{W} + H \tan^{-1} \frac{1}{H} - (H^2 + W^2)^{1/2} \tan^{-1} \frac{1}{(H^2 + W^2)^{1/2}} \right)$

Chapter 10

By E. Amani

X.1 The view factor

• Calculation



Figure 13.6
© John Wiley & Sons, Inc.

Figure 13.5
© John Wiley & Sons, Inc.




Figure 13.4
© John Wiley & Sons, Inc. All rights reserved.

Chapter 10

By E. Amani

X.1 The view factor

• Important relations

- Reciprocity Relation (proof: exercise)

$$A_i F_{ij} = A_j F_{ji} \quad (4.10)$$

- Summation rule: For an enclosure of N surfaces with conditions 1-3 (proof: exercise)


$$\sum_{j=1}^N F_{ij} = 1 \quad (5.10)$$

- For a concave surface:

$$0 < F_{ii} \leq 1$$

- For a convex or flat surface:

$$F_{ii} = 0$$



Chapter 10

By E. Amani

X.1 The view factor


• Important relations

- For the enclosure, from N^2 view factors, $N(N - 1)/2$ are independent:

$$N^2 - N - \frac{N^2 - N}{2} = \frac{N^2 - N}{2} = \frac{N(N - 1)}{2}$$


(5.10) (4.10)

$$i = 1, \dots, N$$



- Compound receiver surface

$$F_{i(j)} = \sum_{k=1}^N F_{ik} \quad (6.10)$$



- Compound emitter surface

$$(6.10) \quad \frac{A_j F_{(j)i}}{A_i} = \sum_{k=1}^N \frac{A_k F_{ki}}{A_i} \quad (4.10) \quad F_{(j)i} = \frac{\sum_{k=1}^N A_k F_{ki}}{A_j} \quad (7.10)$$

Chapter 10

By E. Amani


X.1 The view factor

• Important relations

- For the projection of a surface, provided that the projected surface fully covers the original surface:

$$F_{j1} = F_{j1'} \quad j = 2, \dots, N \quad (8.10)$$

$$F_{11'} = F_{12} + F_{13} + \dots + F_{1N} \quad (9.10)$$



Chapter 10

By E. Amani

X.1 The view factor

• Additional techniques (2D geometries)

- Enclosures with 3 flat/convex (non-concave) surfaces:

$F_{11} = F_{22} = F_{33} = 0$
 $(5.10) \quad F_{11} + F_{12} + F_{13} = 1 \xrightarrow{(4.10)} F_{12} + F_{13} = 1$
 $(5.10) \quad F_{21} + F_{22} + F_{23} = 1 \xrightarrow{(4.10)} \frac{A_1}{A_2} F_{12} + F_{23} = 1$
 $(5.10) \quad F_{31} + F_{32} + F_{33} = 1 \xrightarrow{(4.10)} \frac{A_1}{A_3} F_{13} + \frac{A_2}{A_3} F_{23} = 1$

3 unknown, 3 equations

$$F_{ij} = \frac{A_i + A_j - A_k}{2A_i}; \quad i \neq j \neq k = 1, 2, 3 \quad (11.10)$$


Chapter 10

By E. Amani


X.1 The view factor

- Additional techniques (2D geometries)

- Enclosures with 3 flat/convex (non-concave) surfaces
- Intersecting non-concave surfaces:



- Obstacle effect:




Chapter 10

By E. Amani

X.1 The view factor

- Additional techniques (2D geometries)

- Enclosures with 3 flat/convex (non-concave) surfaces
- Intersecting non-concave surfaces
- Obstacle effect
- Hottel's crossed-string method:



$$F_{12} = \frac{A_4 + A_3 - A_6 - A_5}{2A_1} \quad (12.10)$$


Chapter 10

By E. Amani

X.1 The view factor

- Additional techniques (2D geometries)

- Enclosures with 3 flat/convex (non-concave) surfaces
- Intersecting non-concave surfaces
- Obstacle effect
- Hottel's crossed-string method
- A point source and a surface:




Chapter 10

By E. Amani

X.1 The view factor

- Additional techniques (2D geometries)

- Enclosures with 3 flat/convex (non-concave) surfaces
- Intersecting non-concave surfaces
- Obstacle effect
- Hottel's crossed-string method
- A point source and a surface
- Geometrical symmetry:




Chapter 10

By E. Amani

X.1 The view factor

- Exercise: $F_{13} = ?$



Chapter 10

By E. Amani


X.2 Blackbody Radiation Exchange

- Two black-body surfaces:

$$(2.10) \quad q_{i \rightarrow j} = A_i J_i F_{ij}, \quad J_i = E_{bi} = \sigma T_i^4$$

$$q_{ij} = q_{i \rightarrow j} - q_{j \rightarrow i} \quad q_{ij} = A_i F_{ij} E_{bi} - A_j F_{ji} E_{bj} \quad (4.10)$$

Net radiation exchange from
i to j



Chapter 10

Figure 13.8
© John Wiley & Sons, Inc. All rights reserved.

By E. Amani

X.3 Enclosures with opaque, diffuse, gray surfaces

- Surface radiative resistance

$$(7.9) \quad q_{i,rad} = A_i (J_i - G_i)$$

$$J_i = E_i + \rho_i G_i = \varepsilon_i E_{bi} + (1 - \varepsilon_i) G_i \quad \rho_i = 1 - \alpha_i = 1 - \varepsilon_i \quad G_i = \frac{J_i - \varepsilon_i E_{bi}}{1 - \varepsilon_i}$$

$$q_i = \frac{E_{bi} - J_i}{(1 - \varepsilon_i) / \varepsilon_i A_i}$$

Suggests a surface radiative resistance of the form

Chapter 10

By E. Amani

X.3 Enclosures with opaque, diffuse, gray surfaces

- Geometrical resistance

$$q_{i \rightarrow j} = A_i J_i F_{ij} \quad q_{j \rightarrow i} = A_j J_j F_{ji}$$

$$q_{ij} = q_{i \rightarrow j} - q_{j \rightarrow i} = A_i F_{ij} (J_i - J_j) = \frac{J_i - J_j}{(A_i F_{ij})^{-1}}$$

Suggests a space or geometrical resistance of the form


Chapter 10

By E. Amani

X.3 Enclosures with opaque, diffuse, gray surfaces

- For an enclosure

$$q_i = q_{i,rad} = \sum_{j=1}^N q_{ij} = \sum_{j=1}^N A_i F_{ij} (J_i - J_j) = \sum_{j=1}^N \frac{J_i - J_j}{(A_i F_{ij})^{-1}} \quad (16.10)$$



Chapter 10

By E. Amani

X.3 Enclosures with opaque, diffuse, gray surfaces

- Methodology of analysis

- If q_i is given for surface i , use Eq. (16.10):

$$q_{i,rad} = \sum_{j=1}^N \frac{J_i - J_j}{(A_i F_{ij})^{-1}} \quad (16.10)$$

- If T_i is given for surface i , use Eq. (17.10):

$$\frac{(14.10)}{(16.10)} \quad \frac{E_{bi} - J_i}{(1 - \varepsilon_i)/\varepsilon_i A_i} = \sum_{j=1}^N \frac{J_i - J_j}{(A_i F_{ij})^{-1}} \quad (17.10)$$


- N equations for N unknowns ($J_i; i = 1, \dots, N$)

Chapter 10


By E. Amani

X.4 Radiation shield

- Reduction in radiation exchange between two surfaces
- High reflectivity (low $\alpha = \varepsilon$) surface(s)




X.5 Multimode effects



6.10 Sample problems

A long rod heater of diameter $D_1 = 10 \text{ mm}$ and emissivity $\varepsilon_1 = 1.0$ is coaxial with a well-insulated, semicylindrical reflector of diameter $D_2 = 1 \text{ m}$. A long panel of width $W = 1\text{m}$ is aligned with the reflector and is separated from the heater by a distance of $H = 1\text{m}$. The panel is coated with a special paint ($\varepsilon_3 = 0.7$), which is cured by maintaining it at 400 K . The panel is well insulated on its back side, and the entire system is located in a large room where the walls and the atmospheric, quiescent air are at 300 K . Heat transfer by convection may be neglected for the reflector surface.

- Sketch the equivalent thermal circuit for the system and label all pertinent resistances and potentials?
- Expressing your results in terms of appropriate variables, write the system of equations needed to determine the heater and reflector temperatures, T_1 and T_2 , respectively. Determine these temperatures for the prescribed conditions?
- Determine the rate at which electrical power must be supplied per unit length of the rod heater.



Chapter 10

By E. Amani

The end of chapter 10

Chapter 10

By E. Amani