



 PT. MNA SERANG	WORKING INSTRUCTION		WI/MNASRG-E&I-19-001	
	THERMAL OVERLOAD RELAY REACTIVE MAINTENANCE	Dept.	ENGINEERING	
		Section	E&I	
		Revision	0	
		Effective Date		
		Page	1 of 1	

Kegiatan Maintenance / Maintenance Activity




Matikan sumber energi terkait dan lakukan pemasangan LOTO pada breaker dan key switch (Shut down the energy & LOTO the preaker & key Switch)

Bersihkan debu-debu dan material asing yang menempel pada kontak-kontak relay. (Clean the dust and dirt materials on the relay contacs)



Lepaskan baut yang menempel pada Terminal & lepaskan TOR . (Remove the screw which connected to the terminal & Unplug the TOR)

Pasang TOR yang baru & kencangkan baut . (Connect the new TOR & tighten the screw)



setting arus sesuai dengan perhitungan nilai arus maksimum (Set the current setting based on the max current calculation)

Lakukan pengetesan fungsional relay dengan alat overload relay tester (Test functionality of relay by using overload relay tester device)