

 PT. MNA SERANG	WORKING INSTRUCTION THERMAL OVERLOAD RELAY PREVENTIVE MAINTENANCE	WI/MNASRG-E&I-19-003	
		Dept.	ENGINEERING
		Section	E&I
		Revision	0
		Effective Date	
		Page	1 of 1

Instruksi / Instruction Pre-Action / Pre-Action
--




Siapkan dokumen ceklis, peralatan pembersih, penggaris dan spidol marker (<i>Prepare checklist document, cleaning tools, ruler, and LOTO</i>)	Koordinasi dengan tim produksi (<i>Coordinate with the production team</i>)
---	---




Siapkan JSA, Work Permit LOTO dan form LOTO (<i>Prepare JSA, LOTO Work Permit and LOTO form</i>)	Matikan sumber energi terkait dan lakukan pemasangan LOTO pada breaker dan key switch
--	---

Pembersihan dan Inspeksi / Cleaning and Inspection



Bersihkan debu-debu dan material asing yang menempel pada kontak-kontak relay. (<i>Clean the dust and dirt materials on the relay contacts</i>)	Periksa kekencangan koneksi terminasi pada tiap terminal. (<i>Check tightening of each terminal terminations</i>)
---	---



Pastikan nilai setting arus sudah sesuai dengan perhitungan nilai arus maksimum (<i>Ensure the current setting is proper with max current calculation</i>)	Lakukan pengetesan fungsional relay dengan alat overload relay tester (<i>Test functionality of relay by using overload relay tester device</i>)
--	--