

 PT. MNA SERANG	WORKING INSTRUCTION	WI/MNASRG-E&I-19-008	
		Dept.	ENGINEERING
	GFCI TESTING	Section	E&I
		Revision	0
		Effective Date	01-Sep-19
		Page	1 of 1

pengujianGFCI / <i>GFCI Testing</i>			
KUSUM-MECO Model: KM 1812 EL 	KYORITSU Model: 5406 A 	SONEL Model: MRP-201 	
Siapkan dokumen & alat ukur (<i>Prepare document & measurement tools</i>)			Siapkan Kabel Lead sesuai socket peralatan yang akan diukur (<i>prepare the lead cable according to the csocket tested</i>)
			
Masukkan kabel lead ke dalam alat tester dan masukkan plug ke dalam socket outlet yang sudah diproteksi RCD. (<i>Insert the lead cable into the tester device and insert the plug into the socket outlet that is protected by the RCD to be tested. </i>)			Atur parameter tegangan dan frekuensi pengukuran sesuai dengan spesifikasi sumber listrik yang digunakan (<i>Set voltage and frequency parameter to be appropriate with existing power source specification. </i>)
			
Pastikan indikasi level tegangan dan indikasi N-E, P-N & P-E menyala hijau. (<i>Ensure indication od voltage level and N-E, P-N & P-E indication are lit green </i>)			