

Instrument Gauge Calibration

First step: Inform the workshop operation content, inform the operation purpose, and sign the work ticket.



Second step: Prepare the document & Fluke 3130 Portable Calibrator



Third step: Close the needle valve, make sure the needle valve already close



Fourth step: Remove the Instrument Gauge from the needle valve/vessel



Fifth step: Install the Instrument Gauge to the Fluke 3130 Portable Calibrator according to this setup



The sixth step: Open the pressure calibrator valve to start the instrument gauge calibration process



Seventh step: Record the instrument gauge reading measurement to the form. When reading the instrument gauge, the calibrator eye's should be perpendicular with the instrument gauge



Eighth step: Do the instrument gauge data analysis and do the calculation of calibration data

Equipment Reading	Nilai Aktual	Uncertainty	Koreksi	Result
		95%		
Bar	Bar	Bar	Bar	
0,000	0,000	0,251	0,000	PASSED
1,000	1,005	0,251	0,005	PASSED
2,000	2,007	0,251	0,007	PASSED
4,000	4,005	0,251	0,005	PASSED
6,000	6,005	0,251	0,005	PASSED

Nineth step: Give a seal tape to the instrument gauge to avoid leakage



Tenth step: Install the instrument gauge to the needle valve/vessel



Eleventh step: Make sure we install the instrument gauge correctly then open the needle valve



Twelveth step: Put the calibration sign to the instrument gauge that have been calibrated

