

A detailed diagram of a 16-pin connector layout. The pins are arranged in a grid-like fashion with various labels: A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S. The layout includes a central 16-pin header with pins numbered 1 through 16. Pins 1-4 are on the top row, 5-8 on the second row, 9-12 on the third row, and 13-16 on the fourth row. Pins A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S are arranged around the central header. Pins A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S are arranged in a grid-like fashion. Pins A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S are arranged in a grid-like fashion.

1. SPARE Fuse
2. SPARE Fuse
3. -
4. -
5. DOME Fuse
6. EFI Fuse
7. HORN Fuse
8. AM2 Fuse
9. ST Fuse
10. -
11. H-LP LH Fuse
12. H-LP RH Fuse
13. -
14. -

- A. ST Relay
- B. FAN NO. 2 Relay
- C. FAN NO. 1 Relay
- D. -
- E. EFI Relay
- F. A/C MG Relay
- G. HORN Relay
- H. DRL NO. 5 Relay
- I. HTR SUB1 Relay