
LMS291-S05 to NI 9871 Wiring Diagram



Pin	Signal
1	GND
2	CTS+
3	RTS+
4	RxD+
5	RxD-
6	CTS-
7	RTS-
8	TxD+
9	TxD-