## PROJECT 10073 RECORD CARD

1. DATE  3. DATE-TIME GROUP  Local  GMT  5. PHOTOS  D No	2. LOCATION  1900 A Bast Yokota Japan  4. TYPE OF OBSERVATION  Ground-Visual Ground-Radar  Air-Visual Air-Intercept Radar  6. SOURCE		000 000 000	Possibly Balloon  Was Aircraft Probably Aircraft Possibly Aircraft  Was Astronomical Probably Astronomical Possibly Astronomical
7. LENGTH OF OBSERVATION	8. NUMBER OF OBJECTS	9. COURSE	000	Insufficient Data for Evaluation
10. BRIEF SUMMARY OF SIGHTING		11. COMMENTS		

ATIC FORM 329 (REV 26 SEP 52)

COUNTRY OF ACTIVITY REPORTING	(Leave blank)		
USA (MATS)			
AIR INTELLIGENCE IN	ORMATION REPORT	T	
COUNTRY OF AREA REPORT CONCERNS	DATE OF INFORMATION		
Pacific Wake Island-Japa	an 26 Apr 61		
HQ WESTAF	27 Apr 61.	SRI STATUS (If applicable)	
		CANCELED/COMPLETE	
PREPARING INDIVIDUAL	DATE OF REPORT	SRI NO.	
Major V. L. Sadowski	27 Apr 61	SRI NO.	
NAME OR DESCRIPTION OF SOURCE	EVALUATION	ACTIV	
Pan American Airways	A-1	ADDITIONAL INFORMATION ON (Date)	
REFERENCES (RAIR Subject, previous reports			
SUBJECT (Descriptive title. Use individue)	connects for connects subjects		
Unidentified Object	reports for securate subjects)		
011200 1021200 00,000			
SUMMARY (Give summery which highlights unless report can be fully stated on AF F	the salient factors of narrative repor	t. Begin narrative text on AF Form 112a	
	raft #N-729 PA enroute fr	Company of the Compan	
AB encountered unidentified			
Yokota AB. Object struck a:	ircraft on right wing root	between fuselage and	
		Z 26 April. Damage consist-	
ed of cracked rib assembly a	orward spar station 15 an	d bent rairing assembly	
30401011 10 00 10.			
The undersigned inspected	the aircraft upon its ar	rival at Travis AFB at	
0220 Z 27 April. 1st Office			
the skin of the aircraft.			
to amouth out the contour.			
light fairing. The crew me:			
	Capt. Capt. 1st Off.	and and	
Co-Filot			
It is probable that the a	iroraft may have made or	tact with a Rawi. sonde re-	
leased by the WM Unit locate			
		12 00.	
	/	VERNON L. SADOWSKI USAF	
	A DEPOUTATION	TUNNENT TO SATINGUEST	
1 NCL5	W.T.T.T.OVED:	Major USAF	
		Major USAF Chief, Intel. Br.	
ISTRIBUTION BY OFIGINATOR (Except USAF an	d file. Indicate Dunt M'or and capies	w/o inclosures, if applicable;	
E. MATS			
		the United States within the scaning of the	

an unsurharized person is prohibited by law.

Explanate Laws, little 18, U.S.C., Section 793 and 794, Its transmission or the revelution of its contents in any manner to

O 260345Z ZEX
FM FEA TCC TACKIKAWA AB JAFAN
TO ROWZKS/WCP TCC TRAVIS AFB CALIF
ROHPBG/MPA TCC HICKAM AFB HAWAII
ROWZBN/PCA TCC TRAVIS AFB CALIF

INFO ROWZKS/WTCOS TRAVIS AFB CALIF

BT

UNCLAS FEA TCC 26-D-13 PD TRIP 747/25 ACFT 729 ARRIVED YOKOTA WITH STRUCTURAL DAMAGE TO RIGHT WING ENCOUNTERED AT 31/000 FT 1000 MILES FROM YOKOTA EXTENT OF DAMAGE UNKNOWN AT PRESENT TIME PE ETIC AND ETD INDEFINITE WILL ADVISE PD BT

26/03462 APR ROAPFB

P 260631Z

PM HQ 4503 AIRIRNSFWG TACHIKAWA AB JAPAN

TO RJEDAA/MATS SCOTT AFB ILL

RJWZDL/WESTAF TRAVIS AB CALIF

RJWZNFK/DEPUTY IG FOR SAFETY NORTON AFB CALIF

BT

UNCLASEFTO WGOS 26-D-21. SPECIAL HANDLING REQUIRED IAW PROVISION PARS 49A AND 52 AFR 62-14.

A. N-729 PA

B. PAN AMERICAN AIRWAYS

- C. ENROUTE FROM WAKE ISLAND TO YOKOTA AB.
- D. AIR
- E. 149
- F. NONE
- G. NONE
- H. EMROUTE WAKE-YOKOTA AT 31,000 FEET PILOT FELT AND HEARD MUFFLED THUMP.

  OBJECT STRUCK RIGHT WING ROOT BETWEEN FUSELAGE AND RIGHT LANDING LIGHT.

  AIRCRAFT LANDED YOKOTA 0047Z 26 APR. DAMAGE CONSISTED OF CRACKED RIB

  ASSEMBLY FORWARD SPAR STATIN 16 AND BENT FAIRING ASSEMBLY STATION 16 TO

  75.
- I. NONE
- J. MATS REPRESENTATIVE CAPTAIN FRED X HEAM.
- K. ADDITIONAL INFO. STATUS OF AIRCRAFT AWAITING REPORT OF PAN AMERICAN AND BOR NG STRUCTURAL ENGINEERS AND F.A.A. THIS REPORT CONSIDERED AS COMPLETING REQUIREMENTS OF FAR 3 MATSUF 1 AFR 62-14.

BT

26/0700Z APR RJAPFB