



Project Management Folder — Updated Sitemap

Eb-ODM Execution / Engineering Services / Project Management · Proposed structure · 16 Aug 2026

122

PROJECT FOLDERS

12 → 15

R&D PM SUB-FOLDERS

5

NEW AREAS

3

FIXES TO EXISTING

305

PROCESS STEPS TO SUPPORT

The current project folder carries **Project Folder - R&D PM** with twelve unnumbered sub-folders, **Project Folder - SCS** with seven numbered stages, two MoMs and two audit checklists loose at root. It was designed around design and procurement. The process now runs to 305 steps including 52 test steps, 62 build steps 14 audit-checklist steps and 19 DFM/DFT gate steps — and the folder has nowhere to put most of that output.

1 · Proposed structure

<Project ID>/	e.g. Eb-21-EL-287-01-1879
— 00-Audit-Checklist-PM.xlsx	one name, no variants
— 00-Audit-Checklist-Product-x-Production.xlsx	
— 01-MoM/	
Client-MoM.docx · Internal-MoM.docx	
— 02-Project-Folder-R&D-PM/	numbered – logical order, not alphabetical
— 01-Input-from-Client/	questionnaire · risk plan · testing parameters · client spec
— 02-Approach-Solution-Architecture/	
— 03-LLD-HLD/	LLD · HLD · project plan · budget · delivery schedule
— 04-Project-Timeline-and-Report/	steps tracking · milestone tracker · manufacturing sheet
— 05-Tech-Data-Product-Data/	
— 06-Inventory/	
— 07-Test-and-Compliance/	NEW
— Test-Reports/	HW · FW · Enclosure · System
— Compliance-Certificates/	cert + the build revision it covers
— Field-Trial/	
— UAT-Sign-Off/	
— 08-DFx-and-Manufacturing-Readiness/	NEW – the manufacturability gate, PM side
— 01-DFx-Consolidation/	all three tracks in one view + cross-track dependencies
— 02-DFMA-and-MFA/	DFMA report · manufacturing flow analysis
— 03-Release-Authorisation/	the record that authorises fab and assembly spend
— 04-Lessons-Learned/	what the checklist did not ask → house standard update
— 09-Builds/	NEW
— EVT/ — DVT/ — PVT/	each: build record · BOM used · yield · issue log
— 10-Commercials/	
— 11-Contracts-and-Legal/	
— 12-Feedbacks-and-ECN/	+ ECN-Register.xlsx
— 13-Roadblocks-and-Learnings/	one name – 6 projects still say "Roadblocks"
— 14-Presentation-Documentation/	
— 15-User-Manual-Product-Datasheet/	
— 03-Project-Folder-SCS/	keep the 7 numbered stages
— 1. Inputs from R&D - Clients/	
— 2. MCMA/	MERGED – phase column replaces the duplicate tree
— 3. Quotation shared with the client/	
— 4. Commercials/	
— 5. Contracts & Legal/	
— 6. Production/	1. Pre-EMS · 2. EMS · 3. Post EMS

└─ 7. Delivery & Fulfilment/

└─ **04-Handover-and-Closure/**

Code-Docket/ · Handover-Acknowledgement/ · Warranty-Terms/ · Closure-Record/

└─ **99-Archive/**

mirrors the tree above

NEW

NEW

2 · The five additions

ADDITION	TYPE	WHY IT EARNS ITS PLACE
07-Test-and-Compliance	NEW	The largest gap. The process now carries 52 test steps including compliance certificates, field trial and UAT sign-off, and the PM folder has nowhere for any of it. Certificates in particular need a PM-side home — they are commercial artefacts a client will ask for, not engineering files to be buried inside a PCB folder.
08-Builds	NEW	Prototype, Pilot and Mass Production are 62 steps between them with no folder anywhere. Build evidence currently lands in Assembly or nowhere at all. EVT / DVT / PVT gives each build an identity, which is also what makes yield comparable between builds.
08-DFx-and-Manufacturing-Readiness	NEW	The manufacturability gate had no PM-side home at all. DFMA and MFA reports, the product-level DFX consolidation across hardware, firmware and enclosure, and the written authorisation that releases fabrication and assembly spend are all programme artefacts a client and an auditor will ask for. The board-level DFX evidence stays engineering-side in the PCB ID folder; this is the half the PM owns.
04-Handover-and-Closure	NEW	Post-delivery work has no home. The code docket is the formal end-point of engineering obligation — once submitted, documentation is the only source of information. Today it is emailed and forgotten.
99-Archive	NEW	One archive per project, so superseded material stops sitting beside current material and nobody has to guess which revision is live.

3 · The three fixes to what already exists

FIX	TYPE	EVIDENCE FROM THE CRAWL
Lock the folder names	FIX	Project Folder - R&D PM, Project Folder - R&D and Project File - R&D are the same folder — 9 of 122 use a variant. The audit checklist has three spellings: Audit_Product_Checklist, Audit_Product X Production_Checklist, Audit_Production_Checklist. This is why conformance reads 80% when the real figure is higher — the folder is present under a name the count does not recognise.
Merge the two MCMA trees	FIX	The Lifelong project carries MCMA and MCMA for Prototype — nine duplicated sub-folders and the same three vendor PO templates in both. One tree with a phase column removes the duplication and the ambiguity about which one is current.
Number the R&D PM sub-folders	FIX	Unnumbered means alphabetical, which puts Approach before Input from Client and Commercial before LLD. The order people work in is not the order they see.

4 · Conformance today, and what the fixes recover

ITEM AT PROJECT ROOT	PRESENT	%	NOTE
Project Folder - SCS	105 / 122	86%	Best performing; still missing from 17 projects
Project ID-Client MoM	102 / 122	84%	—
Audit_ProductXProduction_Checklist	102 / 122	84%	3 competing filenames
Audit_PM_Checklist	99 / 122	81%	Trailing-space variant in use
Project Folder - R&D PM	97 / 122	80%	+9 under a variant name
Project ID-Internal MoM	91 / 122	75%	31 projects have none
Feedback & Learning	53 / 122	43%	Not in the template — projects add it themselves

Nothing reaches 90%. Thirteen of the 122 project folders have neither an R&D PM nor an SCS folder — they are containers rather than projects. Two of the seven items above are depressed purely by naming drift, so locking the names recovers real conformance without anyone filing a single new document.

5 · One thing to resolve before building on it

The commercial half of SCS is unused. After ten months of genuine work on the Lifelong project, client PO, client tax invoice, vendor PO, vendor invoices, contracts, e-way bill and shipment invoice are all still the shipping stub. Delete this after uploadning new files.docx , dated 9 April 2025. Either that work happens in a finance system and those nine folders should come out of the template, or it is not being recorded and the process must force it. Adding structure on top of nine unused folders makes the template heavier without making it truer.

Based on a full crawl of Eb-ODM Execution on 15 Aug 2026: 122 project folders listed, 26 deep-sampled to full depth, and two projects — Eb-21-EL-287-01-1879 and EbX-20-ML-270-01-1042 — crawled node by node. Structure aligned to the 305-step Master Process Flow.