

OPEN HARDWARE / PCB REV A2

pt1



POWER. SERIAL. USB. REPEAT.

A pocket-sized bring-up bench for stubborn hardware.



☒ USB HUB

☒ UART

☒ SWITCHED 5 V

☐ FAULT

ONE-CABLE LAB MULTITOOL

Bring up boards. Lose the spaghetti.

Connect a target, open its console, cycle power, and catch a fault through one host USB-C cable.

☒ 3 external USB ports

☒ Logic-level UART

☒ DTR power control

☐ RI fault status

GET STARTED

Three moves from workbench to first signal:

SCAN THE GUIDE

- 1 Connect host USB-C**
Power and data, one cable.
- 2 Wire target + UART**
UART + switched 5 V.
- 3 Open console + iterate**
Watch, reset, recover, repeat.



lab.electrolama.com/project/pt1