
RAIL CONTACT KEEP SOLDER JOINTS CLEAR
TP2
TP1
C3
R3
R3
R1
R1
C2
C2
C1
5 V ARDUINO ADC
TP3
D1
JP1
U1
R2
R2
J1
5V
3V3
GND
A0
K
A
R6
R6
C4
C4
TP4
R4
R4
R5
R5
R7
R7
QRNG
TP4
1 2 SOURCE
2 3 CONTROL
TP5
TP6
TP7
ED4 A | QRNG INVESTIGATION
TRISHAN BISWAS | REV B
RAIL CONTACT KEEP SOLDER JOINTS CLEAR