
Notes:

- a) R3 only required for 3.3V logic. It can be omitted for 5V logic
 b) The output is inverted. If your UART can not handle an inverted signal you have to use an inverter
 c) Certain 6N138 can not operate from 3.3V (but I had it in my collection). A 3.3V compatible substitute would be the HCPL–270L for instance



TITLE Resol VBus galvanic isolated slave interface		
FILE:		REVISION:
PAGE	OF	DRAWN BY: cls