SPI-Can converter Testing Manual

- 1) Load the hex file in to two microcontrollers (ATMEGA 16).
- Connect the pins as given.
 Connect CS to PINB4 and INT to PIND2. All other pins are shown in the board.
- 3) Open the COM ports using putty. The ports can be seen in device manager.
- 4) Now there will be two comports open. Reset the microcontroller. If ICs are working it will show
 - "MCP2515 is active"
 - "Working in normal mode"
- 5) If the ICs are not working it will show
 - "Error: can not address MCP2515"
- 6) If the two converters were successfully detected then type 12345678 and press "enter" key in either one of the putty terminal.
 - It will display "This message was written to the buffer"
 - And the other terminal will display
 - "Message received" and the sent message 12345678
- 7) Test complete