MORE, MORE, MORE THROUGHPUT



40% of all mobile traffic





DPDK/SPDK



PCI bifurcation

```
CPE_NAME="cpe:/o:centos:centos:7"
HOME_URL="https://www.centos.org/"
BUG_REPORT_URL="https://bugs.centos.org/"
CENTOS MANTISBT PROJECT="CentOS-7"
CENTOS_MANTISBT_PROJECT_VERSION="7"
REDHAT_SUPPORT_PRODUCT="centos"
REDHAT_SUPPORT_PRODUCT_VERSION="7"
[cloud@dut5 ~]$ ssh root@10.80.15.107
Last login: Tue Jan 6 21:00:16 1970 from 10.80.15.68
root@FPA1066GX-DA2:~# cat /etc/os-release
ID="fpa1066qx"
NAME="Wind River Linux"
VERSION="0.10.0.00030"
VERSION_ID="0.10.0.00030"
PRETTY NAME="Wind River Linux 0.10.0.00030"
root@FPA1066GX-DA2:~#
root@FPA1066GX-DA2:~#
root@FPA1066GX-DA2:~#
root@FPA1066GX-DA2:~# cat /proc/cpuinfo
processor
model name
BogoMIPS
                  : 200.00
                 : half thumb fastmult vfp edsp thumbee neon vfpv3 tls vfpd32
Features : half
CPU implementer : 0x41
CPU architecture: 7
CPU variant : 0x4
CPU part
CPU revision
processor
model name
                  : ARMv7 Processor rev 1 (v7l)
BogoMIPS
                  : 200.00
Features : half thumb fastmult vfp edsp thumbee neon vfpv3 tls vfpd32 CPU implementer : 0x41
CPU architecture: 7
CPU variant : 0x4
CPU part : 0xc
CPU revision : 1
                  : Altera SOCFPGA Arrial0
Hardware
Revision
                  : 0000
                  : 00000000000000000
Serial
root@FPA1066GX-DA2:~#
root@FPA1066GX-DA2:~# ovs-
```