

Redmi Note9 no booting, online
maintenance in 9008 mode

This case is provided by Xunwei
Quick Repair Flagship Store.

Machine model:Redmi Note9

Fault image:**no booting, online into 9008 mode**

Maintenance process:


Redmi Note 9 When the mobile phone is in use,screen is black or frozen suddenly appears, and it can't be turned on again.Redmi Note 9 Common Pass

The disease is no booting, and even Connect the power supply brain prompts 9008 mode. Could this machine also be the common failing problem?

Connect the mobile phone to the computer with lighting cable, and the computer prompts you to discover the device. Check the prompt in the device manager. 908 port, which proves that this phone is also common failing problem.



Xt20101Note 9 no booting common failing in online 9008 mode means that there is a problem with the PCB layer circuit under the display chip. Just find the display chip Repeat welding or replace the display chip. Open Redmi Note9 Boardview with Xinzhezao Soft maintenance inquiry software, and find the location of the display chip.



Disassemble the motherboard and compare the position of the display chip with Xinzhezao Soft Boardview. Carry out Repeat welding, Repeat welding on the display chip of the motherboard, and then install the motherboard into the mobile phone. The boot test is normal, so the mobile phone can be repaired.



