


ASUS ZE520KL

RF re-Calibration required Components

Bottom

RF (Bottom)




1. U4501: Transceiver(WTR2965_1)
2. U4701: Primary Ant. SW.
3. U4805: MMPA(MB/LB)
4. U5001: B7/B38/B40/B41 PA
5. U4704: Div Ant. SW.
6. U4702, U4703, U4705, U4706, U4707
7. U4801, U4802, U4803, U4804, U4806, U4807, U4808, U4809, U4810, U4811, U4812, U4814, U4817
8. U4901, U4902, U4903, U4904, U4905, U4906, U4907, U4908, U4909, U4911, U4912, U4913
9. U5002, U5004, U5005
10. U5103, U5105, U5107, U5108, U5109, U5110, U5111, U5112, U5116, U5117, U5118, U5119, U5123

Top

RF (Top)

1. U4401: Transceiver(WTR2965_0)
2. U5104
3. U5113
4. U5102
5. U5121
6. U5124
7. U5115



Top

RF (Top)

1. U1501: eMCP

