




1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
A	SAMSUNG CONFIDENTIAL THIS DOCUMENT CONTAINS CONFIDENTIAL PROPRIETARY INFORMATION THAT IS SAMSUNG ELECTRONICS CO.'S PROPERTY. DO NOT DISCLOSE TO OR DUPLICATE FOR OTHERS EXCEPT AS AUTHORIZED BY SAMSUNG.														
B															
C	SM-M135F (NACHO)_REV0.4														
D															
E	2022.05.03														
F															
G	sheet01 : GSM / WCDMA / LTE RF														
H	sheet02 : TRANCEIVER, DRX														
I	sheet03 : SENSORS, NFC, CONNECTIVITY														
J	sheet04 : NACHO														
K	sheet05 : PMIC, CHARGER, KEY, MOTOR, eMCP, SD/SIM														
L	sheet06 : AUDIO, DISPLAY, SUB FPCB CON														
	sheet07 : CAMERA														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15

Engineer:		
Drawn by:		
REV CHK:	TITLE:	Size:
DOC CTRL CHK:	A30	
MFG ENGR CHK:		
QA CHK:	REV:	Drawing Number:
Changed by:	Date Changed:	Time Changed:
Page 1	Page 2	Page 3





F2007











VBAT



Changed by:	Date Changed:
-------------	---------------

	16
--	----






IF PMIC SM5714

COPY FROM SM-A536B




SAMSUNG CONFIDENTIAL
THIS DOCUMENT CONTAINS CONFIDENTIAL
PROPRIETARY INFORMATION THAT IS
SAMSUNG ELECTRONICS CO.'S PROPERTY.
DO NOT DISCLOSE TO OR DUPLICATE FOR OTHERS
EXCEPT AS AUTHORIZED BY SAMSUNG.


CAMERA



RCAM1_50M(34PIN)_S5KJN1




RCAM2_5M_UW (30pin)_GC5035




FRONT_8M_FF (30PIN)_GC08A3

CAMERA MIPI SWITCH





RCAM3_2M_BOKEH (24PIN)_GC02M1B




CAM PMIC


A13_REV00



SHIELD CAN



LCD SUS Contact, 3.3t



2D BARCODE



SWA_4GB+64GB

REGION
GLOBAL_NFC(A) R7020
GLOBAL_NONNFC(B) R7021
LA_M135M(M) R7022
SWA_E135F(E) R7023

MEMORY
3+32 R7020
4+64 R7021
4+128 R7022
6+128 R7023


BOSS HOLE

BOTH7001
PBA SCREW HOLE

Engineer:	SM-M135F
Drawn By:	
Doc Ctrlr:	
Doc Ctrlr:	
MFG ENGR CHK:	
QA CHK:	
REV:	
Drawing Number:	
Page:	78

Revision :
Manufacture Count :
Charge :
Contact :
Date :
Routing :
Resin :


VX_SETUP(2022-02-11)_HHP
Created date of PCB data : 2022/5/ 4 09:31:15



LFL15869MTC1B787(F1006) : IT'S Wrong Polarity possibility. Check the Pin1
2007-010856(R5000, R5033) : Check! Bottom Surface of Component

VX_Setup(2022-02-08)_HHP_TEST2

Created date of PCB data : 2022/4/ 8 17:01:19



VX_Setup(2022-02-08)_HHP_TEST2

Created date of PCB data : 2022/4/ 8 17:01:19

