

iREPAIR

Title			
<Title>			
Size	Document	Number	Rev
A	<Doc>	<Doc>	<Rev Co
Date:		Saturday, September 29, 2018	Sheet 1 of 47



iREPAIR

Title			
<Title>			
Size	Document	Number	Rev
A	<Doc>	<Doc>	<Rev Co
Date:		Saturday, September 29, 2018	Sheet 2 of 47



5

4

3

2

1

D

D

C

C

B

B

A

A

iREPAIR

Title			
<Title>			
Size	Document	Number	Rev
A	<Doc>	<Doc>	<Rev Co
Date:		Saturday, September 29, 2018	Sheet 3 of 47

5


4

3

2

1





MSM8953
Control



iREPAIR






MSM8953
EBI


iREPAIR




NOTE:
Asterisks (*) indicate modem power management (MPM) wake-up pins




I2C PULL-UP



NOTE:
Ensure SW sets these GPIOs (Sensor, CTP and Camera I2C bus) to input pull down when the peripherals are powered off to eliminate leakage.



Hw Board ID



GPIO_0	GPIO_0
GPIO_1	GPIO_1
GPIO_2	GPIO_2
GPIO_3	GPIO_3
GPIO_4	GPIO_4
GPIO_5	GPIO_5
GPIO_6	GPIO_6
GPIO_7	GPIO_7
GPIO_8	GPIO_8
GPIO_9	GPIO_9
GPIO_10	GPIO_10
GPIO_11	GPIO_11
GPIO_12	GPIO_12
GPIO_13	GPIO_13
GPIO_14	GPIO_14
GPIO_15	GPIO_15
GPIO_16	GPIO_16
GPIO_17	GPIO_17
GPIO_18	GPIO_18
GPIO_19	GPIO_19
GPIO_20	GPIO_20
GPIO_21	GPIO_21
GPIO_22	GPIO_22
GPIO_23	GPIO_23
GPIO_24	GPIO_24
GPIO_25	GPIO_25
GPIO_26	GPIO_26
GPIO_27	GPIO_27
GPIO_28	GPIO_28
GPIO_29	GPIO_29
GPIO_30	GPIO_30
GPIO_31	GPIO_31

MSM8953
GPIO






MSM8953
MIPI



iREPAIR






MSM8953
RF

iREPAIR





MSM8953
POWER1




iREPAIR





Title	<Title>
Author	<Author Name>
ID	<ID>






MSM8953
GND



iREPAIR








Rev. 01	2023-03-01	1.0	PMI632 Charger
Rev. 02	2023-03-01	1.0	PMI632 Charger
Rev. 03	2023-03-01	1.0	PMI632 Charger
Rev. 04	2023-03-01	1.0	PMI632 Charger
Rev. 05	2023-03-01	1.0	PMI632 Charger
Rev. 06	2023-03-01	1.0	PMI632 Charger
Rev. 07	2023-03-01	1.0	PMI632 Charger
Rev. 08	2023-03-01	1.0	PMI632 Charger
Rev. 09	2023-03-01	1.0	PMI632 Charger
Rev. 10	2023-03-01	1.0	PMI632 Charger



PMI632 Charger


iREPAIR





iREPAIR






PM8953
Control/Interface

iREPAIR



Position	Symbol	Value	Specified range (mm)	Programmed range (mm)	Rated current (mA)	Surface	Part number
51	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
52	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
53	SMPS	1.000	1.00-1.20	1.00-1.08	1000	W	MSM1000
54	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
55	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
56	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
57	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000




PM8953
SMPS

Position	Symbol	Value	Specified range (mm)	Programmed range (mm)	Rated current (mA)	Surface	Part number
51	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
52	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
53	SMPS	1.000	1.00-1.20	1.00-1.08	1000	W	MSM1000
54	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
55	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
56	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000
57	SMPS	0.01	0.01-0.14	0.01-0.08	1000	W	MSM1000

IREPAIR






Title	
GLSINGL_MIR_V1.0	
014	Document Number
01	0100

[illegible]

iREPAIR

Company Name			
Block Title		Test Points	
Project	Tester	Rev	1.0





MEMORY(LPDDR3+EMMC V5.1)

iREPAIR



IREPAIR





IREPAIR




IREPAIR



SMART
PA



REV &
Speaker




R2301和R2302料号HQ182002 5 0 0 0

iREPAIR





AUDIO JACK





iREPAIR




ACCELEROMETER



address of AK09918 is 0Ch




ALS/P SENSOR+Front Flash+Charge LED CONN





iREPAIR




LCD MIPI Common Mode Filter



LCD/TP-Connector



FPS-Connector






LD0 should be WL2810D18-4/TR

LD0 should be WL2810D18-4/TR

iREPAIR






REPAIR







音量 键&开关机 键





iREPAIR







iREPAIR







PCBA AUTOMATIC TEST point




JTAG CONNECTOR



power key +volup to enter 9008 mode




接彈片 TOP



接彈片 BOT

SMT MARK





TP/GND/Shielding

iREPAIR





IREPAIR






Battery Connector



iREPAIR








PRIMARY_ANTENNA



iREPAIR

NOT TO BE USED, COPIED, REPRODUCED IN WHOLE OR IN PART, OR TO BE TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT PERMISSION IN WRITING FROM QUALCOMM TECHNOLOGIES, INC.	
QUALCOMM	
QUALCOMM Technologies, Inc.	
3501 La Jolla Village Drive San Diego, CA 92161-1697 USA	
TITLE	
SHEET NO. 1 OF 1	
DATE: 01/10/2018	
DRAWN BY: J. L. P. / J. L. P.	
CHECKED BY: J. L. P. / J. L. P.	
APPROVED BY: J. L. P. / J. L. P.	





MAY NOT BE USED, COPIED, REPRODUCED IN WHOLE OR IN PART, NOR THE CONTENTS THEREOF, IN ANY MANNER TO OTHERS WITHOUT THE EXPRESS WRITTEN PERMISSION OF QUALCOMM.	 QUALCOMM Technologies, Inc. 10550 N. Tustin Ave., Suite 200 Irvine, CA 92618-1697 TEL: 949.253.3200 FAX: 949.253.3201 WWW.QUALCOMM.COM	QUALCOMM Technologies, Inc. SPTS Miniature Drive San Diego, CA 92121-8714 USA
Copyright © 1996 QUALCOMM Technology, Inc. All rights reserved.	QUALCOMM IS A REGISTERED TRADEMARK OF QUALCOMM INCORPORATED IN THE UNITED STATES AND MAY BE REGISTERED IN OTHER COUNTRIES. OTHER PRODUCT AND BRAND NAMES MAY BE TRADEMARKS OR REGISTERED TRADEMARKS OF THEIR RESPECTIVE OWNERS.	Title REGISTRATION, CELL, MANUFACTURING DATA SHEET Lot: L00P#002 Date: _____

iREPAIR

NOT TO BE USED. CONTENT REPRODUCED IN WHOLE OR IN PART FOR
 ANY PURPOSES EXCEPTED IN OUR PRIOR WRITTEN CONSENT WITHOUT THE
 WRITTEN AND EXCLUSIVE PERMISSION OF QUALCOMM.

THIS DOCUMENTARY IS THE PROPERTY OF QUALCOMM INC. AND IS NOT TO BE
 REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC
 OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION
 STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF
 QUALCOMM INC. © 2010 QUALCOMM Technologies, Inc.
 All rights reserved.

QUALCOMM
 INCORPORATED, 5765 LAKE AVENUE NORTH, CARLSBAD, CA 92008
 TEL: 760.592.7000 FAX: 760.592.7001
 WWW.QUALCOMM.COM

QUALCOMM IS A REGISTERED TRADEMARK OF QUALCOMM
 INCORPORATED. "iREPAIR" IS A TRADEMARK OF QUALCOMM
 INCORPORATED. "iREPAIR" IS A TRADEMARK OF QUALCOMM
 INCORPORATED. "iREPAIR" IS A TRADEMARK OF QUALCOMM
 INCORPORATED.

[illegible]

B4/66 DPX

[illegible]

B2 DPX

The schematic diagram shows a circuit with a 100k resistor, a 100nF capacitor, and a 100k resistor. The circuit is powered by a 5V supply and includes a 100k resistor, a 100nF capacitor, and a 100k resistor. The output is labeled B2_DPX.

[illegible][illegible]

5

4

3

2





1

D

C

B

A

**B38/41 DRx****B1/2/4/66 DRx****B40 DRx**

5

4





3

2

1

iR&PAIR





DRX LB

NOT TO BE USED, REPRODUCED, OR COPIED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF QUALCOMM TECHNOLOGIES, INC. QUALCOMM TECHNOLOGIES, INC. 10000 N. Tustin Ave. Orange, CA 92668 © 2010 QUALCOMM TECHNOLOGIES, INC.	QUALCOMM QUALCOMM IS A REGISTERED TRADEMARK OF QUALCOMM TECHNOLOGIES, INC. IN THE U.S. AND OTHER COUNTRIES. ALL RIGHTS RESERVED.	QUALCOMM Technologies, Inc. 5775 Marvellous Drive San Diego, CA 92121-0174 U.S.A. Title DRX LB Rev 1.0 Author DRX LB
---	---	--

iREPAIR





5

4

3

2

1

D

D

C

C

B

B

A

A

iREPAIR

Title			
<Title>			
Size	Document	Number	Rev
A	<Doc>	<Doc>	<Rev>
Date:		Saturday, September 29, 2018	Sheet 41 of 47

5

4

3

2

1



5

4

3

2

1

D

D

C

C

B

B

A

A

iR&PAIR

Title			
<Title>			
Size	Document	Number	Rev
A	<Doc>	<Doc>	<Rev>
Date:		Saturday, September 29, 2018	Sheet 42 of 47

5

4


3

2

1



QET4101




iREPAIR



WIFI 2.4G

E4405

NC



WLAN_FEM

NOT TO BE USED, COPIED, REPRODUCED OR IN ANY MANNER FOR ANY PURPOSES WITHOUT THE WRITTEN PERMISSION OF QUALCOMM. THIS TECHNICAL DATA MAY BE SUBJECT TO U.S. AND INTERNATIONAL EXPORT CONTROLS AND RESTRICTIONS. IT IS THE RESPONSIBILITY OF THE USER TO OBTAIN THE NECESSARY EXPORT PERMITS AND LICENSES FOR THE USE OF THIS DATA IN ANY COUNTRY. Copyright © 2014 Qualcomm Incorporated. All rights reserved.	QUALCOMM QUALCOMM Technologies, Inc. 3501 La Jolla Village Drive San Diego, CA 92161-1614 U.S.A.	Task WLAN_FEM Company Project Version Revision
---	---	---

iREPAIR



[illegible]



NOT TO BE USED, COPIED, REPRODUCED OR PUBLISHED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF QUALCOMM INCORPORATED. QUALCOMM INCORPORATED IS NOT PROVIDING THIS DOCUMENT WITHOUT THE EXPRESS OR IMPLIED WARRANTY OF NON-INFRINGEMENT.

QUALCOMM INCORPORATED MAY BE SUBJECT TO U.S. AND INTERNATIONAL EXPORT CONTROLS. IT IS THE USER'S RESPONSIBILITY TO OBTAIN ANY NECESSARY EXPORT PERMITS.


Copyright © 2016 QUALCOMM Technologies, Inc.
All rights reserved.



QUALCOMM IS A REGISTERED TRADEMARK OF QUALCOMM INCORPORATED. IT IS THE USER'S RESPONSIBILITY TO OBTAIN ANY NECESSARY EXPORT PERMITS.

QUALCOMM INCORPORATED IS NOT PROVIDING THIS DOCUMENT WITHOUT THE EXPRESS OR IMPLIED WARRANTY OF NON-INFRINGEMENT.

WCN3615



WCN3680B

NOT TO BE USED, COPIED, REPRODUCED IN WHOLE OR IN PART FOR ANY COMMERCIAL PURPOSES WITHOUT THE WRITTEN PERMISSION OF QUALCOMM. QUALCOMM AND THE QUALCOMM LOGO ARE REGISTERED TRADEMARKS OF QUALCOMM INCORPORATED. ALL OTHER TRADEMARKS, SERVICE MARKS OR REGISTERED PATENT NAMES, INCLUDING THE QUALCOMM LOGO, ARE THE PROPERTY OF THEIR RESPECTIVE OWNERS. Copyright © 1998 QUALCOMM Technologies, Inc. All rights reserved.	 QUALCOMM AND THE QUALCOMM LOGO ARE REGISTERED TRADEMARKS OF QUALCOMM INCORPORATED. ALL OTHER TRADEMARKS, SERVICE MARKS OR REGISTERED PATENT NAMES, INCLUDING THE QUALCOMM LOGO, ARE THE PROPERTY OF THEIR RESPECTIVE OWNERS.	QUALCOMM Technologies, Inc. 5775 Moorpark Drive San Diego, CA 92121-4774 USA
Copyright © 1998 QUALCOMM Technologies, Inc. All rights reserved.	QUALCOMM IS A REGISTERED TRADEMARK OF QUALCOMM INCORPORATED IN THE UNITED STATES AND MAY BE REGISTERED IN OTHER COUNTRIES. OTHER PRODUCTS AND BRAND NAMES MAY BE TRADEMARKS OR REGISTERED TRADEMARKS OF THEIR RESPECTIVE OWNERS.	Title 800MHz/CDMA, MM, GSM, GPRS, J-AS, DPHS, 1 Rev RevF002

i

REPAIR

WVCI500UD

NOT TO BE USED: COPIES, REPRODUCED IN WHOLE OR IN PART, OR OTHERWISE DERIVED IN ANY MANNER, FOR PURPOSES WITHOUT THE WRITTEN PERMISSION OF QUALCOMM. THIS INFORMATION MAY NOT BE SUBJECT TO U.S. AND INTERNATIONAL EXPORTATION AND RE-EXPORTATION CONTROLS. IT IS THE POLICY OF QUALCOMM TO FULFILL ALL EXPORT AND RE-EXPORTATION LAWS AND REGULATIONS. Copyright © 2010 QUALCOMM Technologies, Inc. All rights reserved.	 QUALCOMM IS A REGISTERED TRADEMARK OF QUALCOMM INCORPORATED. "i" AND "REPAIR" ARE TRADEMARKS OF QUALCOMM INCORPORATED. "WVCI500UD" IS A TRADEMARK OF QUALCOMM INCORPORATED.	QUALCOMM Tech QUALCOMM Technologies, Inc. 12000 E. Main Avenue San Diego, CA 92121
--	--	---