











REVISION RECORD			
ITW	ECO NO.	APPROVED:	DATE:




I2C BUS PULL UPS



COMPANY: <Company Name>			
TITLE: <Title>			
DRAWN: <Drawn By>	DATE: <Drawn Date>	CODE: <Code>	SIZE: <Size>
CHECKED: <Checked By>	DATE: <Checked Date>	DRAWING NO: <Drawing Number>	REV: <Revision>
QUALITY CONTROL: <QC By>	DATE: <QC Date>	A0<Drawing Number>	
RELEASED: <Released By>	DATE: <Release Date>	SCALE: <Scale>	SHEET: 30 30





REVISION RECORD			
LTB	ECO NO	APPROVED	DATE





COMPANY: <Company Name>			
TITLE: <Title>			
DRAWN: <Drawn By>	DATE: <Drawn Date>	CODE:	SIZE:
CHECKED: <Checked By>	DATE: <Checked Date>	DRAWING NO:	
QUALITY CONTROL: <QC By>	DATE: <QC Date>	REVISION:	
RELEASED: <Released By>	DATE: <Release Date>	SCALE: <Scale>	
SHEET: 6x		30	

REVISION RECORD			
LT#	FIELD NO.	APPROVED:	DATE:



COMPANY: <Company Name>			
TITLE: <Title>			
DRAWN: <Drawn By>	DATED: <Drawn Date>	CODE: <Code>	
CHECKED: <Checked By>	DATED: <Checked Date>	SIZE: A0	DRAWING NO: <Drawing Number>
QUALITY CONTROL: <QC By>	DATED: <QC Date>	REV: <Revision>	
RELEASED: <Released By>	DATED: <Release Date>	SCALE: <Scale>	
SHEET: 6 of 30			

REVISION RECORD			
LIB	ECO NO.	APPROVED	DATE




COMPANY: <Company Name>

TITLE: <Title>

DRAWN: <Drawn By>	DATE: <Drawn Date>	CODE:		SIZE:	DRAWING NO:	REV:
CHECKED: <Checked By>	DATE: <Checked Date>	<Code>		A0	<Drawing Number>	<Revision>
QUALITY CONTROL: <QC By>	DATE: <QC Date>	SCALE: <Scale>		SHEET: 12 30		
RELEASED: <Released By>	DATE: <Release Date>					

REVISION RECORD			
LYR	ECO NO	APPROVED	DATE




COMPANY: <Company Name>

TITLE: <Title>


DRAWN: <Drawn By>	DATE: <Drawn Date>	CODE:	SIZE:	DRAWING NO:	REV:
CHECKED: <Checked By>	DATE: <Checked Date>				
QUALITY CONTROL: <QC By>	DATE: <QC Date>	<Code>	A0	<Drawing Number>	<Revision>
RELEASED: <Released By>	DATE: <Release Date>	SCALE: <Scale>		SHEET: 19	30

REVISION RECORD			
LTB	ECO NO.	APPROVED	DATE






COMPANY			
<Company Name>			
TITLE			
<Title>			
CODE	SIZE	DRAWING NO.	REV.
<Code>	A0	<Drawing Number>	<Revision>
SCALE	<Scale>	SHEET	30

REVISION RECORD			
LTR	ECO NO:	APPROVED:	DATE:





		COMPANY: <Company Name>				
		TITLE: <Title>				
DRAWN: <Drawn By>	DATED: <Drawn Date>					
CHECKED: <Checked By>	DATED: <Checked Date>	CODE:	SIZE:	DRAWING NO:		REV:
QUALITY CONTROL: <QC By>	DATED: <QC Date>	<Code>		A0<Drawing Number>Revision		
RELEASED: <Released By>	DATED: <Release Date>	SCALE: <Scale>			SHEET 15 30	

A



Note: For Cable detection

Main Camera B 8M





Module	Sensor IC	DOVDD	DVDD	AVDD	AFVDD
IM2836D1.2-4/TR	IM2836D1.2-4/TR	1.8V	1.05V	2.8V	1.8V

Main Camera A 64M




Module	Sensor IC	DOVDD	DVDD	AVDD	AFVDD
IM2836D1.2-4/TR	IM2836D1.2-4/TR	1.8V	1.05V	2.8V	1.8V







Main Camera C 2M
2M FF



Main Camera D 5M
2M AF




REVISION RECORD			
LTR	ECO NO.	APPROVED:	DATE:




COMPANY: <Company Name>			
TITLE: <Title>			
DRAWN: <Drawn By>	DATE: <Drawn Date>	CODE: <Code>	SIZE: <Size>
CHECKED: <Checked By>	DATE: <Checked Date>	DRAWING NO: <Drawing Number>	REV: <Revision>
QUALITY CONTROL: <QC By>	DATE: <QC Date>	A0<Drawing Number>Revision>	
RELEASED: <Released By>	DATE: <Release Date>	SCALE: <Scale>	SHEET: 19 30

REVISION RECORD			
LTB	ECO NO.	APPROVED	DATE

HAPTIC




SUB_FPC




OVP

$V_{ovp} = 1.2 * (1 + R1/R2)$

N-MOS OVP





Battery Connector



Sider Key

Signal	Description
KPSNS0	Volume Up
PM_RST_N	Volume Down
KYPD_Pwr_N	POWER_ON
PM_RST_N + KYPD_Pwr_N	Hardware Reset



EN=L,SEL1/2=L,Ä-Ë USBÍÐÄ£»EN=L,SEL1/2=H D+/D-Í½Ó£-ÇÐ»»·Íð³µç

COMPANY			
<Company Name>			
TITLE			
<Title>			
DRAWN	DRAWN By	DATED	DATED Date
CHECKED	Checked By	DATE	Checked Date
QUALITY CONTROL	QC By	DATED	QC Date
RELEASED	Released By	DATED	Release Date
CODE			
A0<Drawing Number>Revision			
SHEET 20 30			


REVISION RECORD			
LTR	ECD NO:	APPROVED:	DATE:

D

C



B

A



BAD MARK POINT

MARK POINT




		COMPANY: <Company Name>			
		TITLE: <Title>			
DRAWN: <Drawn By>	DATED: <Drawn Date>				
CHECKED: <Checked By>	DATED: <Checked Date>	CODE:	SIZE:	DRAWING NO:	REV:
QUALITY CONTROL: <QC By>	DATED: <QC Date>	A0<Drawing Number>Revision>			
RELEASED: <Released By>	DATED: <Release Date>				
		SCALE: <Scale>	SHEET: 38 30		


DRAWN: <Drawn By>		DATED: <Drawn Date>		<Title>				
CHECKED: <Checked By>		DATED: <Checked Date>						CODE:
QUALITY CONTROL: <QC By>		DATED: <QC Date>		<Code>	A0<Drawing Number>			<Revision>
RELEASED: <Released By>		DATED: <Release Date>		SCALE: <Scale>	SHEET: 20 30			

REVISION RECORD			
LTR	ECO NO:	APPROVED:	DATE:


GPS_2G_5G_ANT CHO




2G_5G_WLAN_CH0



5G wifi ANT CH1




2G_WLAN_CH1_ANT



GPS

High rejection saw



		COMPANY: <Company Name>			
		TITLE: <Title>			
DRAWN: <Drawn By>	DATED: <Drawn Date>				
CHECKED: <Checked By>	DATED: <Checked Date>	CODE:	SIZE:	DRAWING NO:	REV:
QUALITY CONTROL: <QC By>	DATED: <QC Date>	<Code>		A0<Drawing Number>Revision>	
RELEASED: <Released By>	DATED: <Release Date>	SCALE: <Scale>	SHEET: 20 30		

