







Sheet #	Content	Sheet #	Content	
01.	Table of Content	33.	WTR3925	
02.	Revision History	34.	TXM_MMMPA	
03.	Block Diagram	35.	PRX_DUPLEXER	
04.	SM6115_CONTROL	36.	DRX_SAW	
05.	SM6115_GPIO	37.	QET4101	
06.	SM6115_EBI01	38.	WCN3950	
07.	SM6115_MIPi-CSi&DSI	39.	WIFI_GPS	
08.	SM6115_WCSS&RF			
09.	SM6115_PWR_1			
10.	SM6115_PWR_2			
11.	SM6115_PWR_3			
12.	SM6115_DECAPs			
13.	SM4250_GND			
14.	PM4250_HK_IO			
15.	PM4250_BUCKs_S1-S8			
16.	PM4250_LDOS			
17.	PMI632_Control			
18.	PMI632_Charger			
19.	PMI632_LCD&VIB&LED&Flash			
20.	eMMC&LPDDR4			
21.	eMMC&LPDDR4_Power			
22.	Battery&USB_IF			
23.	Audio_codec			
24.	EAR&Smart_PA			
25.	CAMERA_IF			
26.	SENSOR			
27.	SIM_TF			
28.	KEY&TEST_POINT			
29.	SUB_CONN			
30.	Display_IF			





























PM6225 part looks fine, but one important point is that GPIO1 should not be used for other purpose. It is part of power on sequence to enable eLDO for USB SS_DP please refer 80-26896-41 document

Title		<Title>
Size	Document Number	Rev
C	<Doc>	<Rev Code>
Date:	Thursday, September 07, 2023	Sheet 14 of 58


C1501 VPH_PWR BULK CAPS. DISTRIBUTE THESE ALL OVER PM6225



S1A-2A: FTS510 0.8V default 8000mA Ipeak 8110.00mA APC
S3A-4A: FTS510 0.8V default 8000mA Ipeak 8480mA CX, MODEM
S5A: HFS510 0.912V default 4000mA Ipeak 3620.00mA EBI, MX, nLDO
S6A: HFS510 1.352V default 4000mA Ipeak 1560mA LDO
S7A: HFS510 2.04V default 2500mA Ipeak 2350mA LDO
S8A: FTS510 1.128V default 4000mA Ipeak 1790mA LDO, LPDDR4x







Title		<Title>	Rev
Size	Document Number	<Doc>	
C			<Rev Code>
Date:	Thursday, September 07, 2023	Sheet 15 of 58	




Regulator	Circuit type	I _{RATED} (mA)	Default on booting voltage (V) ¹	Specified range (V)	Programmable range (V)	Default on
L1	N800	800	1.0	0.95–1.15	0.312–1.304	Y
L2	N300	300	0.848	0.488–0.988	0.312–1.304	Y
L3	N800	800	0.8	0.4–1.08	0.312–1.304	Y
L4	N300	300	0.928	0.488–1.0	0.312–1.304	Y
L5	MV P50	50	2.98	1.85–3.05	1.504–3.544	Y
L6	N1200	1200	0.624	0.57–0.85	0.312–1.304	Y
L7	N800	800	1.256	1.2–1.3	0.312–1.304	Y
L8	N300	300	0.664	0.4–0.728	0.312–1.304	Y


Regulator	Circuit type	I _{RATED} (mA)	Default on booting voltage (V) ¹	Specified range (V)	Programmable range (V)	Default on
L9 ²	LV P800	800	1.8	1.8–2.0	1.504–2.000	Y
L10	LV P150	150	1.8	1.7–1.9	1.504–2.000	Y
L11	LV P800	800	1.8	1.7–1.95	1.504–2.000	Y
L12	LV P300	300	1.8	1.62–1.98	1.504–2.000	Y
L13	LV P300	300	1.8	1.5–1.95	1.504–2.000	Y
L14	LV P800	800	1.8	1.7–1.9	1.504–2.000	N
L15	MV P150	150	3.128	2.92–3.23	1.504–3.544	Y
L16	LV P150	150	1.8	1.7–1.9	1.504–2.000	N
L17	N300	300	1.304	1.15–1.39	0.312–1.304	N
L18	N300	300	1.232	1.1–1.312	0.312–1.304	Y
L19	MV P150	150	1.8	1.62–3.3	1.504–3.544	N
L20	MV P150	150	1.8	1.62–3.3	1.504–3.544	N
L21	MV P600	600	2.704	2.4–3.6	1.504–3.544	N
L22 ³	MV P600	600	2.96	2.95–3.3	1.504–3.544	Y
L23	MV P800	800	3.304	3.2–3.4	1.504–3.544	N
L24	MV P800	800	2.98	2.7–3.6	1.504–3.544	Y



Charger SC8541




BATTERY




默认不贴


OVP





Battery Ecrypt IC




Flash LED Driver




Title <Title>			
Size C	Document Number <Doc>		Rev <Rev Code>
Date:	Thursday, September 07, 2023 Sheet 19 of 56		




DCDC UFS3.1 VCCQ_1V2




DCDC UFS3.1 VCC_2V5




PA FOR SPK




Sub MIC



PA FOR RECEIVER




Earphone Audio




相机配置: 108M (兼容64M) +8M UW+2M Macro

Main Camera 108M/64M

经验: XXX使用C-PHY的摄像头时, 出现摄像头概率性不出图的问题。
后查出与C-PHY的驱动能力相关, 调试时需留意此问题




Front Camera 16M




POWER LDO


Main DVDD 1V_108M



Main DVDD 1.05V_50M




Macro Camera 2M




Macro摄像头工作时, Main的IOVDD也要上电。
否则I2C无法通信


WIDE Camera 8M(UW)




Main AFVDD 2.8V




Main AVDD 2V2(108M) 2V8(50M)




Front+Wide+Macro CAM AVDD 2V8



Main+Front+Wide+Macro CAM IOVDD



UW+Front Camera DVDD 1.2V




Front Camera DVDD 1.05V




		Module ID	Sensor	I2C	Eeprom	I2C	DRIVER IC	I2C	AVDD	DVDD	IOVDD	AFVDD
Main	108M								2.2	1	1.8	2.8
	50M								2.8	1.1	1.8	2.8
	64M								2.8	1.1	1.8	2.8
	64M								2.8	1.05	1.8	2.8
Front	8M								2.8	1.2	1.8	NA
Wide	8M								2.8	1.2	1.8	NA
Macro	2M								2.8	1.58V	1.8	NA

位号	输入源	输出: 电源网络名	电源应用
U2516	VPH_PWR	CAM_AVDD1_2V8	Front+Wide+Macro+Main(64M) AVDD 2.8V
U2517	VPH_PWR	MAIN_CAM_AVDD2_2V2	Main(108M) AVDD 2.2V
U2580	VPH_PWR	MAIN_CAM_AVDD2_IP05	108M&64M Main DVDD 1.05V
U2510	VREG_STA 2.84V	CAM_DVDD1_1.2V	Wide & Front DVDD 1.2V
U2582	MAIN_CAM_DVDD2_IP05&VREG_BGA	MAIN_CAM_DVDD2_IP05	108M&64M Main DVDD 1.05V 前置 I camera LDO
U2507	VPH_PWR	Main_AFVDD_2.8V	108M&64M Main AFVDD 2.8V
U2509	VREG_STA 2.84V	CAM_IOVDD_1V8	Main+Front+Wide DVDD + Macro IOVDD 1.8V 测试时暂时用1.8V, 选型时需注意Drop 电压




8M WIDE Camera

2M Macro Camera




A+G-Sensor




操作需注意：
1、远离热源
2、远离应力中心与重灾区
3、远离强电流与CPU

IRLED




M SENSOR




保护Msensor使用，
比M sensor高一些的便宜电容即可

FP-Sensor




布线需注意：
1、走线必须从连接器先接TVS再到电阻
2、TVS与电阻需成直线加最长走线为力主左右包地
3、驱动测试时需注意ESD机制的设计，当电源共用时避免SAR与ALS-PS sensor 失效


PL -sensor




LCM BTB



SUB BTB



USB EMI




CTP_AVDD 3.0V

预留 CTP_DVDD 1.8V


LCM_VCCI 3.0V






OLED_IOVDD 1.8V

默认使用焊接电阻（焊盘已遮通），不贴EMI Filter




SIM_SD CARD DET






SAR sensor




Title		
40_RF_SARSensor		
Size	Document Number	Rev
B	<Doc>	1.0
Date:	Thursday, September 07, 2023	Sheet 40 of 58


WTR3925_PWR




SDR735_TX_RX




SDR735_GND




RF_FBRX




RF_TXM



















PA Therm





R3923 and C3991 close to PA, and located in the same layer





GND




48_RF_TX			RevCode
ID	Document Number	Owner	
Issued: September 07, 2023			Revised: 08 of 58



50_RF_TRX_MHB




RF DRX DiFEM



拉美&泛欧: MXD98B1DB
泛亚: MXD98A3WB 两者PTP




B5 DRX




B1/4/66 DRX



B8 DRX




B3 DRX




B12/13/17 DRX




B2 DRX



B20/28 DRX




B32 DRX



B38/41 DRX

Co-Pad:L5140&C5167





B7+B40+B38/41 DRX

Co-Pad:L5114&C5121


Title		
51_RF_DRX_DIFEM		
Size D	Document Number <Doc>	Rev 1.0
Date	Thursday, September 07, 2023	Sheet 51 of 58

RF_QET4101










ANT_B32_DRX




File		
53_RF_ANT		
Size D	Document Number <Doc>	Rev 1.0
Date:	Saturday, September 23, 2023	Sheet 53 of 58









TYPE-C Connect




SUB Connect




SPK




MIC



Marks point




MAIN ANT



接地


同轴线夹子

螺丝接地孔




Title		<Title>
Size	Document Number	Rev
C	<Doc>	<Rev Code>
Date	Friday, August 18, 2023	Sheet 2 of 4

SD+SIM CARD









SIM1 CARD



SIM卡

SIM2 CARD





1. 本设计采用74181 ALU芯片实现4位并行加法器。
 2. 74181 ALU芯片的引脚图如下：
 3. 74181 ALU芯片的功能表如下：
 4. 74181 ALU芯片的时序图如下：
 5. 74181 ALU芯片的封装图如下：
 6. 74181 ALU芯片的供应商如下：
 7. 74181 ALU芯片的参考价格如下：
 8. 74181 ALU芯片的替代品如下：
 9. 74181 ALU芯片的替代品如下：
 10. 74181 ALU芯片的替代品如下：