

地	0	0	0	0	0L	0	0	地
	J_UATA							
	534	388	307	775	775	775	775	

地	0	0	0	地
	J_UAT2（中间 地）			
	0L	500	500	

0	347	347	0	541	287	715	435	0	0L	0L	0	0L	0L	640
	J3900													
	619	561	0	590	0	0L	351	0	0L	0L	0	0L	640	

647		
349	J4300	860
349		593
698		715
0L		793
728	0	793
728		0

598		
0	J4000	713
0		709
286		0
714		0
0L		433
350		0L
0		0L
345		0
345		0L
546		0L
0L		0
692		0L
0	0L	
694		351

0			540		
702	J4500	728	322	J4500	322
421		728	540		322
348		399	540		345
737		354	0		353
0		542	346		785
0		542	739		716
0		542	322		322
			540		

693		
347	J4200	693
292		0
0L		347
716		0
0		0L
352		0L
0L		0
0L		0L
0		0L
0		

545		
0	J4530	574
393		0L
393		643
0		0
410		246
410		318
0		308
410		309
410		330
0		

721		
0	J3500	0
720		320
800		319
319		319
439		

0		
0	J3200	654
0		370
672		370
0		

321		
246	J5700	321
667		321
690		0L
594		633
692		0L
0L		472
0L		0L
0L		319
0		0L
320		317
320		0
0		0
320		319
320		319
0		0
320	319	
320	319	
0		

598	
591	833
591	0
832	700
地	728
0L	500
728	451
350	0
350	0L
0	728
697	100
728	0
342	684
869	684
400	684
332	684
440	0
346	591
440	591
0	833
591	400
591	400
834	400
0L	

Single floor

0		
0L	J5800	0L
0L		0L
0L		0L
667		652
0L		0L
0L		0L
0		733
0		0
0L		722
0		0L
0L		670
722		0L
732	690	
652	677	
0		

0		
774	JLAT_A	0
0L		480
775		0
775		0
776		0
0L		0
0L		0
307		0
532		0
388		0
0		

鑫智造会员
cscaczcy提供

测量设备：福禄克187

Measuring equipment: fluke 187

Measuring equipment: fluke 187