

ZB501KL RF_BR/PH_SKU 教育訓練

Presented by:

Date: 2016/

Agenda

- Overview
- LTE Function Placement
- FA issue

Agenda

- Overview
- LTE Function Placement
- FA issue

ZB501KL Band_BR


ZB501KL

2G: 850/900/1800/1900 3G: 1/5/8

FDD-LTE: 1/3/7/28A/28B

TDD-LTE: B38

ZB501KL RF Overview



ZB501KL Placement

Bottom View

DRX
Spring

WIFI/BT/GPS
Spring

GPS


BT/WiFi/FM

2/3/4G


DTV

ZB501KL Placement

Top View





Key Components Location






Agenda

- Overview
- **LTE** Function Placement
- FA issue



LTE/WCDMA B1 TX





LTE/WCDMA B1 PRX






LTE/WCDMA B1 DRX





WCDMA B5 TX





WCDMA B5 PRX






WCDMA B5 DRX





WCDMA B8 TX





WCDMA B8 PRX







WCDMA B8 DRX





LTE B3 TX





LTE B3 PRX







LTE B3 DRX





LTE B7 TX





LTE B7 PRX



LTE B7 DRX



LTE B28A TX



GFU9802
GFU9805

GFCON981

GFCON4703

GFU4905

Main board BOT



Sub board T

H9912



H9906

Sub board BOT





LTE B28A DRX





LTE B28B TX





LTE B28B PRX





LTE B28B DRX





LTE B38 TX



LTE B38 PRX




LTE B38 DRX







- ACLR-

- Check GFL4809 Voltage.
- Check RLC around GFU4601 and GFU4801.




DCDC SKY87006-11






GSM 850 TX







GSM 850 PRX






GSM 900 TX







GSM 900 PRX







GSM 1800 TX






GSM 1800 PRX



GSM 1900 TX



GSM 1900 PRX



- XO Cal Fail-
 - PC8613 and PC8629 short.
- Internal Cal Fail
 - Check GFC4525



Agenda

- Overview
- LTE Function Placement
- FA issue

Antenna

- GSM/WCDMA/LTE TX & RX
 - Check Antenna Spring on sub-board
 - Check Antenna cable
 - Check Antenna Pattern
- LTE DRX
 - Check Antenna Spring on main board
 - Check Antenna Pattern

Wifi/BT 2.4G TRX



GPS

WFU5307
WFU5306

WFU5310

WFU5402

WFU5401

GFU4501



FM


Main board Top

CON2301



WFU5309

Main board BOT



DTV only for BR SKU

