



Redmi note4 battery replacement leads to no booting


Maintenance process: after the test found that Xiaomi icon appeared during startup, it was restarted continuously. First, the battery was removed, but there was no result. It was judged that there was something wrong with pin. When measuring pin, some clues were found. There were




According to the drawing search, this line is BATT-ON (battery Switch) leading to the power supply MT6351. According to the principle, firstly, Current protection diode is excluded, and then it is directly removed. After the test, the boot is normal, and the fault is solved!



Test battery pin part schematic



Redmi Note 4 Logic Ant Block Diagram & Main Board Component Distribution Diagram



Annotation diagram of red meter n note4 component

Element distribution diagram of hme4 logic board

