Ballard-Fremont Greenways

Stone Way Feedback

March 2023

We are writing on behalf of Ballard-Fremont Greenways with our concerns and suggestions regarding the area around Stone Way N between N 34th and N 36th St.

Problem

The current situation for pedestrians / cyclists / mobility device users near the project areas (SPU + Sellen) is unacceptable. This map highlights the problems (with photos) along with our recommendations.

Recommendations

1) Maintain Accessible Sidewalks and Better Wayfinding

- As can be seen in this map, the sidewalk access near the construction sites is extremely poor.
    i) There are cars blocking the sidewalk regularly in front of Evo along the north side of N 35th.



ii) No parking signs block the south side of N 35th.





iii) The sidewalk on the east side of Interlake Ave is closed limiting access to the preschools.



iv) The sidewalk on the east side of Stone Way N is closed between 35th and 36th due to Sellen Construction.

(1) Cars parked in the bike lane.

(2) Pedestrians walking in the bike lane.



v) The detour signs are wrong or confusing:



- Recommendations
  - i) Ensure all sidewalks remain accessible
    - (1) No cars on sidewalks
    - (2) No “No Parking” signs on sidewalks
  - ii) Maintain an **adjacent** pedestrian reroute along the east side of Stone Way between 35th and 36th
    - (1) Car parking can be removed.
    - (2) Maintain the bicycle lane.
    - (3) There are existing **adjacent** pedestrian reroutes only a block further north along Stone



iii) Maintain sidewalk access to the preschools along Interlake Ave

(1) Reopen the sidewalk on the north side of N 35th (east of Interlake Ave)

(2) Reopen the sidewalk on the east side of Interlake Ave

iv) Fix wayfinding and include signage that directs pedestrians and cyclists from the closure, as well as further away.

2) Signalized Intersection @ 36th


- There are high pedestrian volumes crossing Stone Way N at 36th.



    i) Also many vehicles making turning movements onto Stone from 36th or onto 36th from Stone
    ii) Collision risk is high.
- Recommendations
    i) Install a temporary signalized intersection
        (1) Provides pedestrians a safe way to cross Stone
        (2) Allows protected left turns for vehicles

3) Change Signal Phasing

- High risk of a right-hook at 34th & Stone from vehicles turning right onto N Northlake Way.



- Recommendations
  - i) Change the signal timing
    - (1) No right turning vehicular movements while pedestrians / cyclists are crossing Stone at the south side of N 34th.
    - (2) Existing precedent - pedestrians / cyclists are already given distinct signal phasings further east along the Burke through U District.

4) Relocate Utility Poles

- Utility poles currently block pedestrian / cyclist access to the Burke / sidewalk and poor sightlines result in frequent conflicts



- Recommendations
    i) Relocate the utility poles to less obstructive locations.