Ballard-Fremont Greenways

# Stone Way and 36th Feedback

*December 2023*

We are writing on behalf of Ballard-Fremont Greenways with our concerns and suggestions regarding the intersection of Stone Way N and N 36th St, following the recent incident where a cyclist was hit by a vehicle on December 12th 2023. (https://twitter.com/SDOTtraffic/status/1734752695087689981)

## Problem

The lack of safety treatments for vulnerable road users has now led to a cyclist being hit by a vehicle at this intersection. Large numbers of vulnerable road users use this intersection to cross Stone Way N and, with the work being done at the south end of Stone Way N, there are also large numbers of vehicles passing through this intersection to use N 36th St as a cut through. This leads to many dangerous interactions between vehicles and vulnerable road users, which lead to situations like we witnessed on December 12th.

# Recommendation: Controlled Intersection at 36th

- There are high pedestrian volumes crossing Stone Way N at 36th.



  i) Due to construction on Stone Way N there are many vehicles making turning movements onto Stone from 36th or onto 36th from Stone Way N.
  ii) Vehicles are traveling at high speeds and are unaware about conflict area
  iii) There is no crosswalk for pedestrians to cross this 3+ lane road.
  iv) Collision risk is high.
- Recommendations
  i) Install a four way stop sign treatment at this intersection.
    (1) Provides pedestrians a safe way to cross Stone Way N
    (2) Allows protected left turns for vehicles
    (3) Signals to drivers that a conflict point with pedestrians and other vehicles is approaching
    (4) Slows fast moving traffic in an area of high collision risk
  ii) Install a permanent crosswalk treatment across the north side of 36th across Stone Way N
    (1) Signals to fast moving drivers that pedestrians are crossing