Dufferin Plumbing

Invoice 2291

Bill to: Dana Whitfield
Service address: 61 Brenwick Avenue, unit 3A, Toronto, Ontario
Work: furnace service and filter replacement

Service call and labour, 1.5 hours	$135.00
Furnace filter 16x25x1 MERV 8, 2 at $18.00	$36.00
Flame sensor cleaning and test	$29.00
Subtotal	$200.00
HST (13%)	$26.00
Total due	$226.00

All amounts are in Canadian dollars.
Terms: due within 30 days of the visit.
Payment by e-transfer to service@dufferinplumbing.example.
Technician notes: old filter heavily loaded. Venting checked and clear.

Sample document generated for the Casefile demo. All names are fictional.