Autofocus

Jl. Sidosermo II No.72A Surabaya, Jawa Timur Tel: 031-8497622 Fax: 031-8497611

Laporan Detail Per Mobil

Autocillin

Nomor Polisi L 6004 TY

Tertanggung Candra Dwi Prasetyo Model Kendaraan Daihatsu - Xenia 12/02/2015 Check-in Date Check-out Date 12/02/2015

BIAYA ESTIMIASI

S	na	re	pa	rt

No	Qty	Part No	Nama Part		Harga	Harga disetujui
1	1	PART0007	Low Beam		400000	400,000
				Total Parts (Rp)		400,000
Pan	el					
No		Jenis Perbaikan			Harga	Harga Disetujui
1		Low Beam			120,000	120,000
				Total Panel (Rp)		120,000

BIAYA PENGERJAAN

Sparepart

No Qty	Part No	Nama Part		Harga
1 1	PART0007	Low Beam		400,000
			Total Parts (Rp)	400,000

Data Progres Pengerjaan

No	Tanggal	Jenis Perbaikan	Harga	Progress(%)	Harga Borongan
1	2015-02-12	Afron Belakang (G+C)	200000	100	20,000
			Total Harga Borongan(Rp)		20,000

Data Cat/Bahan

No	Nama	Qty	Keterangan	Harga
1	Cat Merah	1 L		200,000

Total Cat/Bahan (Rp)

Total Harga Borongan(Rp)

200,000

LABA / RUGI	-100,000
Total Biaya Pengerjaan	620,000
Total Biaya Estimasi	520,000

Authorized Signatory / Stamp	