A330 Quick Reference Handbook

NP - NORMAL PROCEDURES NP-NP5 - LOW VISIBILITY PROCEDURES

NP5.5

11-May-15

FAILURE OF EQUIPMENT - EFFECT ON LANDING MINIMA

| Failed or Downgraded Equipment | Effect on Landing Minima | | | | | |
|---------------------------------------|---|--|-----------------------------------|--|--|--|
| | CAT IIIB no DH | CAT IIIB with DH | CAT IIIA | CAT II | CATI | APV, NPA |
| ILS Standby Transmitter | Not Allowed | RVR 200 m | | | | |
| Outer Marker | | | | | | APV - N/A |
| | No effect if replaced by height check at 1 000 ft | | | | Not allowed except if replaced by height check at 1 000 ft | NPA with FAF: No effect unless used as FAF |
| Outer Marker | | | | | | If FAF cannot be identified, non-precision ops cannot be conducted |
| Middle Marker | | | | | | No effect unless used at MAPt |
| RVR Assessment System | At least one RVR value available on aerodrome | On RWYs equipped with two or more RVR assessment units, one maybbe inoperative | | | | |
| Approach Lights | | Not allowed for operations with DH> Not allowed | | | Minima as for NALS | |
| Approach Lights except the last 210 m | | | | Not allowed | Minima as for BALS | |
| Approach Lights except the last 420 m | | | | | Minima as for IALS | |
| Approach Lights Standby Power | | | | | | |
| Edge Lights, Threshold | | | Day: No effect | Day: No effect | Day: No effect Night: Not allowed | |
| Lights and RWY End Lights | | | Night: RVR 550 m | Night: Not allowed | | |
| Centreline Lights | Day: RVR 200 m | | Day: RVR 300 m | Day: RVR 350 m | F/D or auto-land: No effect Otherwise: RVR: RVR 750m | |
| | Night: Not allowed | Not allowed | Night: RVR 400 m | Night: RVR 550 m (auto-land 400 m) | | |
| Centreline Lights Spacing 30 m | RVR 150 m | | | | | |
| | | Day: RVR 200 m | Day: RVR 300 m | | | |
| Touchdown Zone Lights | | Night: RVR 300 m | Night: RVR 550 m, auto-land 350 m | | F/D or auto-land: No effect Otherwise: RVR: RVR 750m | |
| Taxiway Lighting System | | | | | | |

Note:

- 1. Grey shaded areas indicate "no effect".
- 2. Multiple failures of runway lights other than indicated in the table are not acceptable. (components showing "no effect" in respective column are not counted for multiple failures).
- 3. Deficiencies of approach and runway lights are treated separately.
- 4. CAT II or CAT III operations: a combination of deficiencies in RWY lights and RVR assessment equipment is not permitted.
- 5. Failures other than ILS affect RVR only and not DH.
- ${\it 6. The "Whole runway light system" comprises threshold, runway edge, and RWY end lights.}\\$
- 7. For CAT IIIB operation with no DH, at least one RVR value must be available at the aerodrome.
- 8. For "Minima for NALS/BALS/IALS" OMA 8.4.4.2.1.2 CAT I, APV and NPA Minima.