


Yellow triangle in Device Manager under Ports


After install the PL-2303 Drive but the COM Port show yellow triangle, fix it as follow:

1. Find the COM Port:

Right click "My Computer"->Manage->Device Manager->Ports (COM & LPT), check"Prolific USB-to-Serial Comm Port", if no "yellow icon" means install successful or go to step 2 to fix the yellow icon.



- 2. Fix the "Yellow icon".
 - Right click "Prolific USB-to-Serial Comm Port"->Update driver software



Click "Browse my computer for driver software" option



- Click" Let me pick from a lit of device driver on my computer"
- → Let me pick from a list of device drivers on my computer This list will show installed driver software compatible with the device, and all driver software in the same category as the device.
- Choose the "Version 3.3.2.105[10/27/2008]" and click "Next";



Check the Port again and no yellow icon, means install successful.

