Formula sheet for testing materials

Izaak van Dongen

October 17, 2017

1 Material properties

1.1 Stress

The stress is defined as force applied divided by cross-sectional area and denoted as σ

$$\sigma = \frac{F}{A} \tag{1}$$

Hence, stress is measured in Nm^{-2} , which is called Pa (scals).