

Use corrosion preventive compound (C-101) between bushing and horn.

212-M-64-3

Figure 64-3. Tail rotor hub and blade (212-010-701)