





212_IPB_62_0007

Figure 62-7. Hub Assembly, Main Rotor

62-99-00 Page 30

Rev. 8 30 APR 2010

ECCN EAR99