



212_IPB_53_0036

Figure 53-36. Beam Assembly, RH

53-99-00 Page 182

Rev. 8 30 APR 2010

ECCN EAR99