

## **NOTES**

 $\sqrt{1}$ 

On helicopters with steel lift link fitting P/N 212-040-106.

2

Add one additional washer, if required, to obtain cotter pin hole and nut castellation alignment. ensure washers are positioned as shown in view A.

212-M-63-11

Figure 63-11. Transmission mounting hardware