



## MINIMUM OF 4 ROWS OF M7885/6-6-3 RIVETS SPACED 0.72 IN. (18.288 mm) APART EACH SIDE OF DAMAGE



## TYPICAL PATCH REPAIR



SECTION A-A

212\_MM\_32\_0004\_c01

Figure 32-4. Skid Tube (BHT 205-050-400 and 412-050-023) Patch Repair