



NOTE



The 412-040-123-101 quill assembly contains a look alike gear. Ensure pinion has six holes before installation in transmission.

212_MM_63_0057

Figure 63-57. Rotor Brake Quill