

NOTE: Use maximum of three steel washers under each nut to obtain proper thread engagement.

- 1. Bolt (3 places)
- 2. Steel washer (MS20002C4)
- 3. Inboard deck fitting
- 4. Deck fitting shim
- 5. Deck fitting shim
- 6. Steel washer (see note)
- 7. Nut (3 places)
- 8. Bolt (2 places)
- 9. Steel washer (MS20002C4)
- 10. Forward deck fitting

- 11. Deck fitting shim
- 12. Steel washer (see note)
- 13. Nut (2 places)
- 14. Bolt (2 places)
- 15. Steel washer (MS20002C6)
- 16. Aft deck fitting
- 17. Deck fitting shim
- 18. Deck fitting shim
- 19. Steel washer (see note)
- 20. Nut (2 places)

212-M-71-24

Figure 71-24. Aft left mount tripod deck fitting