


Figure 98-64. Component replacement (Sheet 1 of 72)






Figure 98-64. Component replacement (Sheet 2)




Figure 98-64. Component replacement (Sheet 3)




Figure 98-64. Component replacement (Sheet 4)




Figure 98-64. Component replacement (Sheet 5)




Figure 98-64. Component replacement (Sheet 6)




Figure 98-64. Component replacement (Sheet 7)




Figure 98-64. Component replacement (Sheet 8)




Figure 98-64. Component replacement (Sheet 9)




Figure 98-64. Component replacement (Sheet 10)




Figure 98-64. Component replacement (Sheet 11)




Figure 98-64. Component replacement (Sheet 12)





Figure 98-64. Component replacement (Sheet 13)






Figure 98-64. Component replacement (Sheet 14)





Figure 98-64. Component replacement (Sheet 15)








Figure 98-64. Component replacement (Sheet 16)









Figure 98-64. Component replacement (Sheet 17)






Figure 98-64. Component replacement (Sheet 18)




Figure 98-64. Component replacement (Sheet 19)




Figure 98-64. Component replacement (Sheet 20)




Figure 98-64. Component replacement (Sheet 21)




Figure 98-64. Component replacement (Sheet 22)




Figure 98-64. Component replacement (Sheet 23)




Figure 98-64. Component replacement (Sheet 24)




Figure 98-64. Component replacement (Sheet 25)




Figure 98-64. Component replacement (Sheet 26)




Figure 98-64. Component replacement (Sheet 27)

K44B22N -W95A22 -W94A22 NC K44A22N W3A22 -Ε W93A22 -ND NC H60A22 -H59A22 -D ND • NC K12A22 -K42A22 -K10C22 ND NC Q25A22 Q24C22 В Q27F22 -ND NC K37A22 · - K41A22 -ND • WI3A22N -BLK WIID22 -WHT

NO. I EMERGENCY FIRE HANDLE

212-M-98-64-28

Figure 98-64. Component replacement (Sheet 28)

 \mathbb{R}

 $\binom{\mathbb{R}}{\mathbb{R}}$




Figure 98-64. Component replacement (Sheet 29)





Figure 98-64. Component replacement (Sheet 30)






Figure 98-64. Component replacement (Sheet 31)




Figure 98-64. Component replacement (Sheet 32)




Figure 98-64. Component replacement (Sheet 33)




Figure 98-64. Component replacement (Sheet 34)




Figure 98-64. Component replacement (Sheet 35)




Figure 98-64. Component replacement (Sheet 36)




Figure 98-64. Component replacement (Sheet 37)





Figure 98-64. Component replacement (Sheet 38)






Figure 98-64. Component replacement (Sheet 39)




Figure 98-64. Component replacement (Sheet 40)




Figure 98-64. Component replacement (Sheet 41)




Figure 98-64. Component replacement (Sheet 42)




Figure 98-64. Component replacement (Sheet 43)




Figure 98-64. Component replacement (Sheet 44)




Figure 98-64. Component replacement (Sheet 45)




Figure 98-64. Component replacement (Sheet 46)




Figure 98-64. Component replacement (Sheet 47)




Figure 98-64. Component replacement (Sheet 48)






Figure 98-64. Component replacement (Sheet 49)








Figure 98-64. Component replacement (Sheet 50)





Figure 98-64. Component replacement (Sheet 51)



(SEE NEXT SHEET FOR CONTINUATION)

Figure 98-64. Component replacement (Sheet 52)




Figure 98-64. Component replacement (Sheet 53)




Figure 98-64. Component replacement (Sheet 54)




Figure 98-64. Component replacement (Sheet 55)




Figure 98-64. Component replacement (Sheet 56)




Figure 98-64. Component replacement (Sheet 57)




Figure 98-64. Component replacement (Sheet 58)




Figure 98-64. Component replacement (Sheet 59)




Figure 98-64. Component replacement (Sheet 60)




Figure 98-64. Component replacement (Sheet 61)




Figure 98-64. Component replacement (Sheet 62)




Figure 98-64. Component replacement (Sheet 63)




Figure 98-64. Component replacement (Sheet 64)




Figure 98-64. Component replacement (Sheet 65)




Figure 98-64. Component replacement (Sheet 66)




Figure 98-64. Component replacement (Sheet 67)




Figure 98-64. Component replacement (Sheet 68)




Figure 98-64. Component replacement (Sheet 69)





Figure 98-64. Component replacement (Sheet 70)



NOTE

REMOVE JUMPERS WHEN NO. 2 GYRO SYSTEM IS INSTALLED.

Figure 98-64. Component replacement (Sheet 71)

EFFECTIVITY

- (1) 30597 THROUGH 30603 AND 30611 THROUGH 30614.
- 2 30615 THROUGH 30679.
- 8 30680 THROUGH 31221.
- (12) 30940 THROUGH 31221.
- (13) 31222 THROUGH 31256.
- 31257 AND SUBSEQUENT.
- (15) 31222 AND SUBSEQUENT.
- (16) 30504 THROUGH 31206.
- 31207 AND SUBSEQUENT.
- 18 30504 THROUGH 30939.

Figure 98-64. Component replacement (Sheet 72)