

Figure 71-50. Engine air management system exhaust duct repair