

NOTE:

1 REFER TO COMPONENT REPLACEMENT.

212-M-98-40 212-475-021M

Figure 98-40. Secondary lights (S/N 30597 and subsequent)