

MATERIAL: ALUMINUM OR MICA

212-M-63-49

Figure 63-49. Workaid for replacing input drive quill seal