



NOTE:



BENDIX OR COURTER torque transmitters on helicopters S/N 30501 through 30999, 31101 through 31124 and 32101 through 32142 with PT6T-3 engines, are located on gearbox or firewall. These transmitters on S/N 31125 and 32143 and subsequent and helicopters modified by TB 212-81-52 are mounted on the firewall.

212_M_76_5_c01

Figure 76-5. Torque Transmitter Index/Valve Settings