

- 1. Bracket
- 2. Electrical harness
- 3. Bracket
- 4. Washer

- 5. Nut
- 6. Packing
- 7. Scupper
- 8. Cap

- 9. Chip detector
- 10. Screen Tube
- 11. Packing

212-M-63-25

Figure 63-25. Full flow debris monitor