

- 1. U-bolt fwd
- 2. Support fwd upper
- 3. Support fwd lower
- 4. Washer
- 5. Nut
- 6. Crosstube fwd
- 7. Crosstube aft
- 8. U-bolt aft
- 9. Support aft upper
- 10. Support aft lower
- 11. Washer
- 12. Nut

NOTE



Apply a bead of adhesive (C-308) around entire periphery of supports.

212-M-32-1A

Figure 32-1A. Crosstube supports