



NOTES

- 1. Any response similar to that shown above that is within the GATE is cause for rejection.
- 2. The signal that appears to the left of the GATE will be displayed throughout the inspection; it is not considered relevant.

212_MM_62_0005

Figure 62-13. Ultrasonic Equipment Display