QUICK START

SETUP GUIDE



FOR DAHLE SHREDDERS

- UNPACK THE SHREDDER
 - REMOVE SHIPPING/TRANSPORT BOLTS
 - FILL AUTOMATIC OILER

QUICK START- SETUP GUIDE

UNPACK THE SHREDDER

- Cut the shipping straps and remove the top box cover.
- Lift & remove the corrugated box sleeve surrounding the shredder and all packing material.
- Carefully lift the shredder out of the bottom corrugated base.
 (Please note this shredder is suspended on the box and is top heavy.
 Carefully support the shredder while moving to avoid tipping over.)



REMOVE THE SHIPPING/TRANSPORT BOLTS

- Open the shredder door & remove the suspended waste bag.
- Locate the two (or three) recessed shipping bolts inside the cabinet, directly under the cutting head, and remove them. (A hex key) is provided for your convenience.)



FILL THE AUTOMATIC OILER (if applicable)

- Open the cabinet door. If your shredder is equipped with an automatic oiler it will be located on the inside left of the machine.
- Slide open the reservoir & unsrew the black fill cap.
- Pour the oil into the reservoir, tighten the cap, and slide back into shredder.



POWER ON THE SHREDDER

- Install the power cord (*located inside the cabinet*) on the back of the machine & plug it in.
- Be sure the top of the red emergency shutoff switch is depressed.
- Press the bottom button on the round command dial (located on the top cover of the machine). This will turn the shredder on.





49 Vose Farm Road Peterborough, NH 03458 (800) 995.1379 / www.dahle.com



Please see Owner's Manual for complete operating instructions