		4	3	<b>DADICULA</b> 2  1
TEM	QTY	PART NUMBER	DESCRIPTION	PARTS LIST WEBLINK
1	1	frame		3D PRINT ABS
2		Air Zone		3D PRINT ABS
3		MotorBlock		3D PRINT ABS
4		Fan		3D PRINT ABS
5		FrameToPipe		3D PRINT ABS
6	1	DC Brush Motor 24V 150W High Speed Motor with Belt Pulley for DIY Generator Electric Vehicle Motor		https://www.amazon.ca/dp/B082R32F4K/ref=sspa_dk_detail_2?psc=1&pd_rd_i=B082R32F4K&pd_rd_w=zm4Rm8 _rd_p=a14ddd24-c45e-4c01-803e-ab6a335c1c48&pd_rd_wg=dEqW1&pf_rd_r=K9WZF461PM65KRFQD8CK&pd_rd =499ca0f4-b3ed-4d1e-a3d8-348bb5bb667d&spLa=ZW5jcnlwdGVkUXVhbGlmaWVyPUEzVFVHWU9DWjBTOERaJmV 3J5cHRIZElkPUEwNzUwMzc1UllIWjk0V1ZITTBQJmVuY3J5cHRIZEFkSWQ9QTAyNDQ0MTAxNUI1UERNWTA4Tlgmd2l V0TmFtZT1zcF9kZXRhaWwmYWN0aW9uPWNsaWNrUmVkaXJlY3QmZG9Ob3RMb2dDbGljaz10cnVl
7	2	McMaster60355K430_BALL BEARING	STEP AP203	https://www.mcmaster.com/60355k43
8		Crabot 1-4 to 11-32 OR 6MM TO 8MM	012.74.203	https://www.mcmaster.com/6408k9-6408K913 & https://www.mcmaster.com/6408k9-6408K914
9		ANSI B18.22.1 - 1/4 - narrow - Type B	Plain Washer (Inch )Type A	OR M6 WASHER
۱	5		and B	OK MO WASHEK
10	1	ANSI B18.3 - 1/4-20 UNC - 3.25	Hexagon Socket Head Cap	OR SCREW M6 X 80MM
10	Т		Screw	OR SCREW 140 X 6014114
1	<u> </u>	ANSI B18.2.2 - 1/4 - 20		OR M6 NUT
11	2	ANSI B18.2.2 - 1/4 - 20	Hex Nuts (Inch Series) Hex	
2		Unburgles 2/0 v F 1/2	Nut	OR M9 NUT X 140MM
12	4	Unbrako - 3/8 x 5 1/2	Hexagon Socket Head Cap	
12	1	ANCI P10 2 2 2/0 16	Screw	OR MO NUT
13	4	ANSI B18.2.2 - 3/8 - 16	,	OR M9 NUT
		ANCI D10 22 1 2/0	Nut	OD MO MACHED
14	8	ANSI B18.22.1 - 3/8 - narrow - Type A	Plain Washer (Inch )Type A	OR M9 WASHER
			and B	
				DRAWN emile 3/23/2020 CHECKED COVID 19 OPEN SOURCE  QA  TITLE
				MFG APPROVED
				SIZE DWG NO
				В
				SCALE





