## 1 Instruction Set Reference List

		31	25	21	17	13	0	
Formats	c-type:	opcode	rd	rs1	rs2	0		
	i-type:	opcode	rd	rs		18-bit immediate		
	l-type:	opcode	rd		22-bit immediate			
Instructions	NOP:	000000				0		
	SET:	000001	rd	rs		18-bit immediate		
	LOAD:	000010	rd			22-bit immediate		

## ADD

Format c-type: ADD, rd, rs, rs

Format i-type: ADD, rd, rs, immediate Purpose: To add two 32 bit integers