MD. SHOHANUR RAHMAN SHOHAN

22-46013-1




Figure: All LEDs turned ON.




Figure: All LEDs turned OFF after giving vibration to the Tilt Switch