\lm4f\HardwareSerial.cpp:

Warning !!!!!

Ligne 127 uartModule = 2 must be uartModule = 0

Ligne 235 original is begin(baudRate) but baudRate is not passed in function

Ligne 235 begin(9600) assume determined value

```
Add lignes 409-440:
409 void
410 UARTIntHandler1(void)
411 {
412
      Serial1.UARTIntHandler();
413 }
414
415 void
416 UARTIntHandler2(void)
417 {
418
      Serial2.UARTIntHandler();
419 }
420
421 void
422 UARTIntHandler3(void)
423 {
424
       Serial3.UARTIntHandler();
425 }
426 void
427 UARTIntHandler5(void)
428 {
429
       Serial5.UARTIntHandler();
430 }
431 void
432 UARTIntHandler6(void)
433 {
434
       Serial6.UARTIntHandler();
435 }
436 void
437 UARTIntHandler7(void)
438 {
439
       Serial7.UARTIntHandler();
440 }
```

```
Add lignes 441-448
441 //Preinstantiate Object (must be declared here and not in sketch)
442 HardwareSerial Serial(0);
443 HardwareSerial Serial1(1);
444 HardwareSerial Serial2(2);
445 HardwareSerial Serial3(3);
446 HardwareSerial Serial5(5);
447 HardwareSerial Serial6(6);
448 HardwareSerial Serial7(7);
\lm4f\startup gcc.c:
Add lignes 69-74
69 __attribute__((weak)) void UARTIntHandler1(void) {}
70 __attribute__((weak)) void UARTIntHandler2(void) {}
71 __attribute__((weak)) void UARTIntHandler3(void) {}
72 __attribute__((weak)) void UARTIntHandler5(void) {}
73 __attribute__((weak)) void UARTIntHandler6(void) {}
74 __attribute__((weak)) void UARTIntHandler7(void) {}
Modify line 117:
117 UARTIntHandler, to UARTIntHandler1,
Modify line 144:
144 UARTIntHandler, to UARTIntHandler2,
Modify line 170:
170 UARTIntHandler, to UARTIntHandler3,
Modify line 172-174:
```

172 UARTIntHandler, to UARTIntHandler5, 173 UARTIntHandler, to UARTIntHandler6, 174 UARTIntHandler, to UARTIntHandler7,

\lm4f\HardwareSerial.h

```
Add lignes 62-67
62 void UARTIntHandler1(void);
63 void UARTIntHandler2(void);
64 void UARTIntHandler3(void);
65 void UARTIntHandler5(void);
66 void UARTIntHandler6(void);
67 void UARTIntHandler7(void);
Add lignes 74-79
74 extern HardwareSerial Serial1;
75 extern HardwareSerial Serial2;
76 extern HardwareSerial Serial3;
77 extern HardwareSerial Serial5;
78 extern HardwareSerial Serial6;
79 extern HardwareSerial Serial7;
Add Lignes 83-88:
83 extern "C" void UARTIntHandler1(void);
84 extern "C" void UARTIntHandler2(void);
85 extern "C" void UARTIntHandler3(void);
86 extern "C" void UARTIntHandler5(void);
87 extern "C" void UARTIntHandler6(void);
88 extern "C" void UARTIntHandler7(void);
\hardware\lm4f\cores\lm4f\main.cpp
Change:
HWREG(GPIO_PORTD_BASE + GPIO_O_CR) |= 0x8;
To
HWREG(GPIO_PORTD_BASE + GPIO_O_CR) |= 0x80;
\lib\keywords.txt
Add:
Serial5 KEYWORD3
                      Serial
Serial5 KEYWORD3
                      Serial
Serial6 KEYWORD3
                      Serial
Serial7 KEYWORD3
                      Serial
```